

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D

ESTIMATES

Estimate No. : 21998908
Date Estimated : 07/05/2022
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
Mr. Ng Shou Chuan

- ACCOUNT -
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Motor Claims Department

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL
SJN5189P	W203001992	19/2/2009	TOYOTA WISH

DESCRIPTION	ORIGINAL PRICE	NETT
To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident		2,500.00
To spray paint rear bumper, tail end panel and boot lid		2,250.00
To replace PDC sensors, connectors and attachments include resetting and conducting checks for proper function		350.00
To remove and install Rear windscreen glass to facilitate repairs including water leak tests		720.00
To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function		450.00
To remove and install Rear boot compartment carpet and garnish to facilitate repairs		225.00
To carry out body cavity preservation (For cut panel)		450.00
To carry out body cavity preservation		100.00
To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function (For cut panel)		350.00
To replace rear exhaust silencer include alignment and conducting checks for leak and proper function		450.00
Sundries		100.00

DESCRIPTION	UNIT PRICE	QTY	NETT
Bumper trim	1,035.00	1.00	1,035.00
Guide, center rear	153.50	1.00	153.50
Carrier, bumper rear	483.40	1.00	483.40
PDC sensors set	400.00	1.00	400.00

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D

ESTIMATES

Guide for bumper, left	161.15	1.00	161.15
Guide for bumper, right	161.15	1.00	161.15
Left reflector	37.90	1.00	37.90
Right reflector	37.90	1.00	37.90
Toyato wish lettering	72.00	1.00	72.00
Trunk lid	1,239.35	1.00	1,239.35
Trunk lid sealing	144.55	1.00	144.55
Toyata sign	72.85	1.00	72.85
Wish lettering	65.60	1.00	65.60
Rear windscreen sealant	175.35	2.00	350.70
Rear windscreen	620.90	1.00	620.90
Tail trim	390.35	1.00	390.35

Total Labour :	7,945.00
Total Parts :	5,426.30
Total Labour & Parts :	13,371.30
Deduction for Excess :	
Total Repair Costs less E	13,371.30
GST @7%:	935.99
Grand Total :	14,307.29