

BIS AUTOMOBILES

50 Teban Gardens Crescent Singapore 608927
 BIS Automobiles Pte Ltd
 Co-Reg No: 201908170 GST Reg No: 201908170

ESTIMATES

Estimate No. : 21998908
 Date Estimated : 07/05/2022
 Prepared By : Gary Poh Chai Heon

- ESTIMATE REPAIR FOR -
 Mr. Ng Shou Chuan

- ACCOUNT -
 China Taiping Insurance (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909
 Motor Claims Department

*Steve (CLKK)
 24/5/22, 11:07 AM*

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL
SJN5189P	W203001992	19/2/2009	TOYOTA WISH
DESCRIPTION	ORIGINAL PRICE	NETT	
To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident	350 X 3	2,500.00	1050 / 700
To spray paint rear bumper, tail end panel and boot lid	360 X 3	2,250.00	700 1050 /
To replace PDC sensors, connectors and attachments include resetting and conducting checks for proper function		350.00	50 /
To remove and install Rear windscreen glass to facilitate repairs including water leak tests		720.00	150 /
To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function		450.00	50 / 80.00
To remove and install Rear boot compartment carpet and garnish to facilitate repairs		225.00	X
To carry out body cavity preservation (For cut panel)		450.00	X
To carry out body cavity preservation		100.00	X
To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function (For cut panel)		350.00	50 / 50.00
To replace rear exhaust silencer include alignment and conducting checks for leak and proper function		450.00	X
Sundries		100.00	30 /

DESCRIPTION	UNIT PRICE	QTY	NETT
COVER			
Bumper trim / 00	1,035.00	1.00	1,035.00 570 / 456.00
Guide, center rear X 00	153.50	1.00	153.50
Carrier, bumper rear X 00	483.40	1.00	483.40
PDC sensors set X 00	400.00	1.00	400.00 200 / 111 X

LKK AUTOMOBILES

30 Teban Gardens Crescent, Singapore 609927
 LKK Automobiles Pte Ltd
 UEN No: 201328817D GST Reg No: 201328817D

ESTIMATES

BUMPER RETAINER					
	Quota for bumper, left		161.15	1.00	161.15 / 10 56.00
BUMPER RETAINER	Quota for bumper, right		161.15	1.00	161.15 / 10 56.00
	Left reflector	X (M)	37.90	1.00	37.90
	Right reflector	X (M)	37.90	1.00	37.90
	Toyota wish lettering	X (M)	72.00	1.00	72.00
	Trunk lid		1,239.35	1.00	1,239.35 / 991.48
	Trunk lid sealing	1 X (M)	144.55	1.00	144.55
	Toyota sign	X (M)	72.85	1.00	72.85
	Wish lettering	X (M)	65.60	1.00	65.60
	Rear windscreen sealant		175.35	2.00	350.70
	Rear windscreen	X (M)	620.90	1.00	620.90
	Tail trim	X Repair	390.35	1.00	390.35

SUPP ITEMS:				
REPAIR KIT WINDSCREEN	\$131.55	2.00	\$249.95	✓ NEC
BULB LONGLIFE 5W	\$10.85	1.00	\$10.85	✓ NEC
			210.48	
			8.68	

Total Labour :	7,945.00
Total Parts :	5,426.30
Total Labour & Parts :	13,371.30
Deduction for Excess :	
Total Repair Costs less	13,371.30
GST @7%:	935.99
Grand Total :	14,307.29

Steve (LKK)
 17/5/22, 9:30am

with RJUNER
 5 days
 PIP

Resurvey Before Spray

add 1 day = 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be returned by 3pm and is subject to final approval from LKK Auto Company

Accepted by Repairer:
 Signature: _____
 Date: _____