

BIS AUTOMOBILES

50 Teban Gardens Crescent Singapore 608927
BIS Automobiles Pte Ltd
Co-Reg No: 201008170 GST Reg No: 201008170

ESTIMATES

Estimate No. : 21998908
Date Estimated : 07/05/2022
Prepared By : Gary Poh Chai Heon

- ESTIMATE REPAIR FOR -
Mr. Ng Shou Chuan

- ACCOUNT -
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Motor Claims Department

Steve (CLKK)
24/5/22, 11/11/22

REGN. NO. CHASSIS NO. REGN. DATE MODEL
SUN5189P W203001992 19/2/2009 TOYOTA WISH

DESCRIPTION	ORIGINAL PRICE	NETT
To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident	350X43	2,500.00 1050 ✓
To spray paint rear bumper, tail end panel and boot lid	360X43	2,250.00 700 1050 ✓
To replace PDC sensors, connectors and attachments include resetting and conducting checks for proper function		350.00 50 ✓
To remove and install Rear windscreen glass to facilitate repairs including water leak tests		720.00 150 ✓
To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function		450.00 50 ✓
To remove and install Rear boot compartment carpet and garnish to facilitate repairs		225.00 X
To carry out body cavity preservation (For cut panel)		450.00 X
To carry out body cavity preservation		100.00 X
To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function (For cut panel)		350.00 50 X
To replace rear exhaust silencer include alignment and conducting checks for leak and proper function		450.00 X
Sundries		100.00 30 ✓

DESCRIPTION	UNIT PRICE	QTY	NETT
COVER			
Bumper trim	1,035.00	1.00	1,035.00 570 ✓
Guide, center rear	153.50	1.00	153.50
Carrier, bumper rear	483.40	1.00	483.40
PDC sensors set	400.00	1.00	400.00 200-444 X

LKK AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
LKK Automobiles Pte Ltd
UEN No: 2013081170 GST Reg No: 2010081170

ESTIMATES

BUMPER RETAINER	
Bumper, left	161.15
Bumper, right	161.15
Left reflector	37.90
Right reflector	37.90
Toyota wish lettering	72.00
Trunk lid	1,239.35
Trunk lid sealing	144.55
Toyota sign	72.85
Wish lettering	65.60
Rear windscreen sealant	175.35
Rear windscreen	620.90
Tail trim	390.35

161.15	1.00	161.15
161.15	1.00	161.15
37.90	1.00	37.90
37.90	1.00	37.90
72.00	1.00	72.00
1,239.35	1.00	1,239.35
144.55	1.00	144.55
72.85	1.00	72.85
65.60	1.00	65.60
175.35	2.00	350.70
620.90	1.00	620.90
390.35	1.00	390.35

SUPP ITEMS:

REPAIR KIT WINDSCREEN	\$131.55	2.00	\$249.95	✓	NEC
BULB LONGLIFE 5W	\$10.85	1.00	\$10.85	✓	NEC

Total Labour :	7,945.00
Total Parts :	5,426.30
Total Labour & Parts :	13,371.30
Deduction for Excess :	
Total Repair Costs less	13,371.30
GST @7%:	935.99
Grand Total :	14,307.29

Steve (LKK)
17/5/22, 9-30am

With RJNKR
5 days
PIP

Resurvey Before Spray

add 1 day = 6 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary work(s) must be returned by LKK and is subject to final approval from Insurer's Company

Accepted by Repairer

Signature:

Date: