



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300623

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 02/02/2023
Reference CC6/CTI22004323/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 503E
Insured Veh. SMG 1195Z
Claim No. SNM22D203195C02
Policy No. DMPCSNA00037412201
Accident Date 08/05/2022
Inspection Date 10/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22004323/Dpa3q2 Date: 02/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMG 1195Z	Veh. Inspected	SHC 503E
	Policy No.	DMPCSNA00037412201	Coverage (\$)	0.00
	Claim No.	SNM22D203195C02	Excess (\$)	0.00
	Assign From		Assign Date	10/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVKU141337	Colour	YELLOW
	Odometer	482813 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/05/2022	Inspection Date	10/05/2022
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 503E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT / DENTED	2,253.80	2,253.80
1	BONNET HINGE (LH)	TO REPAIR SEE LABOUR	118.70	-
1	BONNET LOCK	BENT	127.30	127.30
1	BONNET INSULATOR	NOT NECESSARY	230.10	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	15.00	-
1	RADIATOR GRILLE	BROKEN	1,409.10	1,409.10
2	FLAP ASSY ACTIVE AIR UPPER (LH/RH) @\$824.60	BROKEN	1,649.20	1,649.20
1	UNIT ASSY -SMART CRU (RADAR SENSOR)	MTG BROKEN	3,061.40	2,910.90
1	FLAP ASSY ACTIVE WIRE	SOCKET BROKEN	765.30	765.30
1	FRONT NUMBER PLATE GARNISH	BROKEN	188.00	188.00
1	FRONT BUMPER COVER	TORN	481.10	481.10
1	FRONT BUMPER TOP COVER	CRACKED	476.30	476.30
1	FRONT BUMPER SPONGE	TORN	186.90	186.90
1	FRONT BUMPER REINFORCEMENT	DENTED	1,136.70	1,136.70
1	FRONT BUMPER REINFORCEMENT ABSORBER (LH)	DENTED	186.50	186.50
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	29.00	-
1	FRONT BUMPER MOULDING CENTRE UPPER	CUT	368.50	368.50
1	FRONT BUMPER MOULDING	TORN	93.60	93.60
1	FRONT BUMPER LOWER STIFFNER	BENT	285.10	285.10
1	FRONT BUMPER LOWER GRILLE	CUT	365.30	365.30
1	FRONT BUMPER LOWER GRILLE MOULDING	CUT / MTG CRACKED	127.60	127.60
1	FRONT BUMPER LIP	SERVICEABLE	35.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$85.00	O/S NOT NECESSARY / N/S BROKEN	170.00	85.00
2	FRONT BUMPER BRACKET (LH/RH) @\$75.00	O/S NOT NECESSARY / N/S BROKEN	150.00	75.00
2	FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$95.00	NOT NECESSARY	190.00	-
10	FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
1	FRONT BUMPER GRILLE (LH)	MTG CRACKED	186.90	186.90

Report Ref No. CC6/CTI22004323/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER AIR DUCT (LH)	NOT NECESSARY	153.80	-
1	DAY LIGHT ,LH	MTG BROKEN	642.50	642.50
1	DAY LIGHT ,WIRE	NOT NECESSARY	585.50	-
1	BUZZER ASSY -PIEZO (LH)	NOT NECESSARY	388.00	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,139.30	1,139.30
1	HEADLAMP (LH)	BROKEN	3,987.30	2,110.30
1	HORN UNIT (LH)	BROKEN	72.80	72.80
1	HORN WIRE	NOT NECESSARY	386.70	-
1	RADIATOR INVERTER	BENT /PUNCTURE	884.80	884.80
1	RADIATOR	BENT / PUNCTURE	710.50	710.50
1	RADIATOR FAN BLOWER MOTOR ASSY	BROKEN	1,459.60	1,459.60
1	RADIATOR AIR GUARD (LH)	BROKEN	76.40	76.40
1	RADIATOR AIR GUARD UPR (LH)	NOT NECESSARY	127.50	-
1	RADIATOR TANK RESERVOIR	NOT NECESSARY	196.50	-
1	FRT PILLAR UPPER COVER-OUTER (LH)	DISLODGE	89.60	89.60
1	FRONT FENDER (LH)	DENTED	490.70	490.70
1	FRONT FENDER SHIELD (LH)	TORN	164.70	164.70
1	AIRCON CONDENSER	BENT / PUNCTURE	663.60	663.60
1	FRT DOOR (LH)	NOT NECESSARY	1,797.20	-
1	FRT DOOR RUBBER	NOT NECESSARY	250.00	-
1	FRONT DOOR HINGE UPPER (LH)	NOT NECESSARY	165.76	-
1	FRONT DOOR HINGE LOWER (LH)	NOT NECESSARY	153.70	-
1	FRONT DOOR CHECK (LH)	NOT NECESSARY	72.98	-
2	FRT SAFETY BELT (ASSY) (LH/RH) @\$648.90	ACTIVATED	1,297.80	1,297.80
2	REAR SAFETY BELT (ASSY) (LH/RH) @\$513.20	ACTIVATED	1,026.40	1,026.40
2	REAR SAFETY BELT GARNISH COVER (LH/RH) @\$398.00	BROKEN / MTG CRACKED	796.00	796.00
1	FRONT WINDSCREEN GLASS	CRACKED	1,558.10	1,558.10
1	FRONT WINDSCREEN MOULDING	NECESSARY	157.30	157.30
1	FRONT WHEEL RIM (LH)	NOT NECESSARY	1,124.20	-
1	FRONT WHEEL HUB ASSY (LH)	NOT NECESSARY	678.50	-
1	FRONT WHEEL HUB CAP	NOT NECESSARY	346.40	-
1	FRONT SHOCK ABSORBER (ASSY) (LH)	NOT NECESSARY	372.50	-

Report Ref No. CC6/CTI22004323/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	372.50	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	1,136.70	-
1	RACK & PINION ASSY	NOT NECESSARY	2,387.40	-
1	STG TIE ROD	NOT NECESSARY	125.60	-
1	STG TIE END	NOT NECESSARY	94.70	-
1	STABILIZER BAR	NOT NECESSARY	326.80	-
1	STABILIZER BAR LINK	NOT NECESSARY	92.10	-
1	FRONT SUSPENSION LOWER ARM (LH)	NOT NECESSARY	596.80	-
1	KNUCKLE ARM (LH)	NOT NECESSARY	663.60	-
1	ELECTRONIC CLUTCH ACTUATOR ASSY	CRACKED	6,345.80	4,386.50
1	DASHBOARD COMPLETE	DAMAGED	4,724.00	1,474.00
1	PASSENGER AIR BAG	ACTIVATED	2,633.00	1,951.20
1	STEERING AIRBAG COMPLETE	ACTIVATED	1,090.90	1,090.90
1	AIRBAG CONTROL MODULE	ACTIVATED	1,243.70	1,243.70
1	KNEE CONTROL AIRBAG MODULE ASSY	ACTIVATED	578.60	578.60
1	STEERING ANGLE ASSY	NOT NECESSARY	786.90	-
1	SENSOR ASSY IMPACT -FRT INPACT	NOT NECESSARY	643.90	-
2	AIRBAG SENSOR (LH/RH) @\$348.10	ACTIVATED	696.20	696.20
1	FRONT BUMPER REINFORCEMENT ABSORBER (RH) (ADDITIONAL)	DENTED	186.50	186.50
1	FRONT BUMPER SIDE GRILLE (RH) (ADDITIONAL)	MTG CRACKED	186.90	186.90
1	DAY LIGHT ,RH (ADDITIONAL)	MTG CRACKED	642.50	642.50
1	HEADLAMP (RH) (ADDITIONAL)	CRACKED	3,987.30	2,110.30
1	FRONT CHASSIS MEMBER (LH) (ADDITIONAL)	TO REPAIR SEE LABOUR	1,314.80	-
1	AIR DUCT (ADDITIONAL)	BROKEN	156.80	156.80
1	ENGINE UNDER COVER (ADDITIONAL)	TORN	469.40	469.40
1	ELECTRONIC CLUTCH PUMP-INVERTER HPCU TRAY (ADDITIONAL)	CRACKED	864.30	864.30
1	INVETER ELECTRIC WATER PUMP ASSY (ADDITIONAL)	BROKEN	651.30	651.30
	LESS 20% DISCOUNT		-13,869.43	-8,686.52
			55,477.71	34,746.08
	NETT ITEMS			
1	EMBLEM -BLUE DRIVE (LH) (N)	NECESSARY	26.60	26.60

Report Ref No. CC6/CTI22004323/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-5.32
			26.60	21.28
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) }	BROKEN	25.00	45.00
1	FRONT NO PLATE TRIM COVER (SN)}	BROKEN	30.00	-
1	COOLANT (SN)	NOT NECESSARY	45.00	-
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORT LOGO (LH) (SN)	NOT NECESSARY	75.00	-
1	FRONT DOOR ADVERTISEMENT LOGO (LH) (SN)	NOT NECESSARY	100.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT ERP BRACKET (SN)	NECESSARY	30.00	30.00
1	FRONT TYRE (SN)	NOT NECESSARY	216.00	-
2	CLUTCH FLUID @\$85.00 (SN)	NOT NECESSARY	170.00	-
1	INVERTER COOLANT (SN)	NOT NECESSARY	65.00	-
			902.00	221.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET HINGE (LH) AND FRONT CHASSIS MEMBER (LH) .		1,800.00	1,000.00
	SPRAY PAINTING CHARGE.		1,600.00	800.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	TRANSFER DOOR MECHANISM FRONT .	NOT NECESSARY	80.00	-
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).	NOT NECESSARY	400.00	-
	RE-SET FRT ABS SYSTEM.	NOT NECESSARY	200.00	-
	REMOVE /REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
	REMOVE/REFIX FUSE BOX,	NOT NECESSARY	120.00	-
	REMOVE/REFIX FRONT WINDSCREEN GLASS .		120.00	80.00

Report Ref No. CC6/CTI22004323/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX ENGINE .	NOT NECESSARY	600.00	-
	REMOVE/REFIX DASHBOARD .}		350.00	180.00
	REMOVE/REFIX AIR BAG /STEERING WHEEL /DASHBOARD /SEAT.}		550.00	-
	RE-PROGRAME AIR BAG & SAFETY BELT SYSTEM.}		550.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.}		550.00	150.00
	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR .}		550.00	-
			8,290.00	2,410.00
GRAND TOTAL			64,696.31	37,398.36

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			29,000.00
---	--	--	------------------

Report Ref No. CC6/CTI22004323/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 503E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 503E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 503E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

