

Case Details

Case Reference Number :

TAX/05/22/2010

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB1668L

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18185-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 04/05/2022 08:22 AM

Vehicle Age(Ig Months) : 6

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
Standard	Main			PANEL-BODY SI OTR FRT-LH	1	235.24	211.72	10.00	211.72	Replace	0	0	Not Give	Xan	
Standard	Main			PANEL-BODY SI OTR MID	1	323.23	323.23	10.00	290.91	Replace	0	0	Not Give	Xan	
Standard	Main			PANEL-BODY SI OTR RR FENDER - LH	1	1,201.52	1,201.52	10.00	1,081.37	Replace	1	0	Repair	R	
Standard	Main			DOOR ASM-RR SI -L	1	2,185.04	2,185.04	10.00	1,966.54	Replace	0	0	Not Give	Xan	
Standard	Main			DOOR ASM-FRT SI -L	1	2,338.76	2,338.76	10.00	2,104.88	Replace	0	0	Not Give	Xan	
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	Xan	
Standard	Main			FENDER ASM-FRT - LH	1	379.80	379.80	10.00	341.82	Replace	1	341.82	Replace	bt ✓	
Standard	Main			FASCIA-RR BPR	1	758.47	758.47	10.00	682.62	Replace	0	0	Not Give	Xan	
Standard	Main			FASCIA-FRT BPR	1	721.66	721.66	10.00	649.49	Replace	1	649.49	Replace	sa ✓	
Standard	Main			STICKER ELECTRIC (LOGO)	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	Xan	

8225.32

Total Spare Part Cost 8,875.13

Surveyor Total 991.31

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 8,875.13

Final Sur Total 991.31

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Final Price(\$)				Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			SENSOR-RR PARK DIST CONT	3	65.00	195.00	175.50	10.00	175.50	Replace	0	0	Not Give	Xm
Standard	Main			MIRROR ASM-O/S RR VIEW - LH	1	478.40	478.40	430.56	10.00	430.56	Replace	0	0	Not Give	Xm
Standard	Main			WHEEL	1	618.07	618.07	556.26	10.00	556.26	Replace	0	0	Not Give	Xm
Standard	Main			BEARING ASM-RR WHL	1	335.40	335.40	301.86	10.00	301.86	Replace	0	0	Not Give	Xm
					1626.87	Total Spare Part Cost					8,875.13	Surveyor Total			991.31
					Lump Sum Discount (%)					0.00	Lump Sum Dis (%)			0	
					Final Spare Part Cost					8,875.13	Final Sur Total			991.31	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	1,800.00	500	
Total:			1,800.00	500.00	✓

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	428.00	200	
3	Main	TO RESPRAY FRONT DOOR LH	428.00	0	Xm
4	Main	TO RESRAY REAR DOOR LH	428.00	0	Xm
5	Main	TO RESPRAY REAR FENDER LH	428.00	200	
6	Main	TO RESPRAY REAR BUMPER	428.00	0	Xm
7	Main	TO RESPRAY RIM	230.00	0	Xm
8	Main	TO RESPRAY VIEW MIRROR	230.00	0	Xm
9	Main	TO RESPRAY SIDE PANEL	230.00	0	Xm
Total:			3,258.00	600.00	✓

Estimate Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0 X	
4	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0 X	
5	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
6	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0 X	
Total:			1,000.00	190.00 /	

6058

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,875.13	991.31
Total Labour Cost	1,800.00	500.00
Total Spray Painting	3,258.00	600.00
Other	1,000.00	190.00
Overall Total	14,933.13	2,281.31
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	2,281.31
Surveyor Approved Amount		2,281.31
No of Repair Days*	6	4
Remarks		part by part repair / resurvey before paint
Surveyor Name		Rasul

Signature

Survey Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

06/05/2022

Acknowledged by Repairer

Signature:

Date:

Save

Clear

Rasul