

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 19/05/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHB1668L
Case Reference Number	TAX/05/22/2010
Registration Date	30/11/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	WANG BOON YEOW (YUAN WENYAO)
Type of Accident	Side Swipe
Accident Date and Time	4/5/2022 4:22 PM
Accident Reported Date and Time	5/5/2022 12:17 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114821
Special Instruction to ARC, if any	LEFT PORTION /NTUC - LKK
Prepared Date and Time	5/5/2022 4:33 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,800.00	\$500.00
Total Spray Cost	\$3,258.00	\$600.00
Total Spare Part Cost	\$8,875.13	\$991.31
Total Other Cost	\$1,000.00	\$190.00
TOTAL COST	\$14,933.13	\$2,281.31 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	05/05/2022 5:06 PM	06/05/2022 3:43 PM
Signature		
Remarks		part by part repair / resurvey before paint

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2205-0207	Invoice Number	
Quotation Date	19.05.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,800.00	\$500.00
Total Labour	\$1,800.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$428.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$428.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$428.00	\$0.00
TO RESRAY REAR DOOR LH	\$428.00	\$0.00
TO RESPRAY REAR FENDER LH	\$428.00	\$200.00
TO RESPRAY REAR BUMPER	\$428.00	\$0.00
TO RESPRAY RIM	\$230.00	\$0.00
TO RESPRAY VIEW MIRROR	\$230.00	\$0.00
TO RESPRAY SIDE PANEL	\$230.00	\$0.00
Total Spray Painting & Panel Beating	\$3,258.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
Total Other Costs	\$1,000.00	\$190.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10345435 AA-SEPP	PANEL-BODY SI OTR FRT-LH	0.00	\$235.24	0.00	\$0.00	Replace	Not Given
		10345435 BB-SEPP	PANEL-BODY SI OTR MID	0.00	\$323.23	0.00	\$0.00	Replace	Not Given
		10345435 CC-SEPP	PANEL-BODY SI OTR RR FENDER - LH	1.00	\$1,201.52	100.00	\$0.00	Replace	Repair
		10380137-SEPP	DOOR ASM-RR SI -L	0.00	\$2,185.04	0.00	\$0.00	Replace	Not Given
		10169203-SEPP	DOOR ASM-FRT SI -L	0.00	\$2,338.76	0.00	\$0.00	Replace	Not Given
			STICKER STRIDES TAXI (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		10236735-SEPP	FENDER ASM-FRT - LH	1.00	\$379.80	10.00	\$341.82	Replace	Replace
		10369261-SPRP	FASCIA-RR BPR	0.00	\$758.47	0.00	\$0.00	Replace	Not Given
		10325882-SPRP	FASCIA-FRT BPR	1.00	\$721.66	10.00	\$649.49	Replace	Replace

X
X
R
X
X
X
X
✓
X
✓

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/05/2022

User ID PohSuan

			STICKER ELECTRIC (LOGO)	0.00	\$21.60	0.00	\$0.00	Replace	Not Given
		10376550-WSD	SENSOR-RR PARK DIST CONT	0.00	\$65.00	0.00	\$0.00	Replace	Not Given
		10728335-SPRP	MIRROR ASM-O/S RR VIEW - LH	0.00	\$478.40	0.00	\$0.00	Replace	Not Given
		10317983	WHEEL	0.00	\$618.07	0.00	\$0.00	Replace	Not Given
		10509505	BEARING ASM-RR WHL	0.00	\$335.40	0.00	\$0.00	Replace	Not Given
Total					\$9,722.19		\$991.31		

X
X
X
X
X
X

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

991.31
 + 500.00
 + 790.00

 2,281.31