

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Xiao Tony

Quotation

DATE : 10.05.2022
 VEH NO : SMC4157K
 MODEL : Honda Vezel
 D O A : 07.05.2022
 YR REF : SNB1609L

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMC4157K (HONDA VEZEL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp <i>new</i>	1	77.00 <i>x.</i>
2	Rear Bumper <i>Distorted.</i>	1	765.40 <i>✓</i>
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	57.00 <i>✓</i>
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	282.20 <i>x</i>
5	Rear Corner Bumper - LH & RH <i>Repair</i>	2	390.00 <i>x.</i>
6	Rear End Panel <i>Distorted</i>	1	585.40 <i>✓</i>
7	Rear End Panel Top Garnish <i>behind</i>	1	98.40 <i>✓</i>
8	Rear End Panel Antenna Sensor <i>new</i>	1	85.20 <i>x.</i>
9	Rear End Panel Buzzer <i>Damage</i>	1	125.50 <i>✓</i>
10	Taillamp - LH & RH <i>LH cut</i>	2	949.20 <i>474.60.</i>
11	Tailgate <i>Distorted</i>	1	1,100.00 <i>✓</i>
12	Tailgate Lock <i>Damage</i>	1	182.50 <i>✓</i>
13	Tailgate Weatherstripe <i>cut</i>	1	186.40 <i>✓</i>
14	Tailgate Reflector - LH & RH <i>cut</i>	2	826.40 <i>✓</i>
15	Tailgate Reflector Sponge Gasket - LH & RH <i>new</i>	2	40.00 <i>✓</i>
16	Tailgate Inner Trimboard <i>behind</i>	1	285.60 <i>✓</i>
17	Tailgate Outer Garnish <i>new</i>	1	325.40 <i>x.</i>
18	Tailgate Damper - LH & RH <i>new</i>	2	365.40 <i>x</i>
19	Tailgate Glass Moulding <i>new</i>	1	145.00 <i>✓</i>
20	Honda Logo <i>new</i>	1	30.40 <i>x.</i>
21	Vezel Emblem <i>new</i>	1	45.90 <i>✓</i>
22	Spare Tyre Panel Top Cover <i>behind</i>	1	306.60 <i>✓</i>
23	Spare Tyre Panel Undercover <i>behind</i>	1	268.20 <i>✓</i>
24	Tools Tray Sponge <i>cut</i>	1	285.40 <i>✓</i>
25	Rear Fender Inner Trimboard - LH & RH <i>behind</i>	2	610.40 <i>✓</i>
26	Rear Exhaust Pipe	1	598.60 <i>x</i>
27	Rear Exhaust Pipe Mounting <i>new</i>	1	32.40 <i>x</i>
28	Rear Exhaust Pipe Gasket	1	35.00 <i>x</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SMC4157K (HONDA VEZEL)

6388.70
5110.96

Less 20%

	9,084.90
	(1,816.98)
\$	7,267.92

S/NETT ITEMS

1	Rear Number Plate <i>Best</i>	1	\$	30.00 ✓
2	Rear Number Plate Holder <i>Relid</i>	1	\$	30.00 ✓
3	Rear Bumper Clips <i>me</i>	1 set	\$	30.00 ✓
4	Rear End Panel Top Garnish Clips <i>me</i>	1 set	\$	20.00 ✓
5	Rear End Panel Sealant <i>me</i>	1	\$	60.00
6	Reverse Sensor <i>Dargd</i>	1	\$	280.00 200. ✓
7	Taillamp Sponge Gasket - LH & RH <i>LH New</i>	2	\$	40.00 20. ✓
8	Tailgate Inner Trimboard Clips <i>New</i>	1 set	\$	30.00 ✓
9	Tailgate Outer Garnish Clips <i>New</i> 570	1 set	\$	20.00 x
10	Tailgate Glass Sealant <i>me</i>	1	\$	60.00 ✓
11	Rear Camera <i>Not me</i>	1	\$	480.00 x
12	Spare Tyre Panel Undercover Clips <i>New</i>	1 set	\$	30.00 ✓
13	Rear Fender Inner Trimboard Clips <i>me</i>	2 set	\$	60.00 ✓
				\$ 1,170.00
Total Parts				\$ 8,437.92

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 800
2	To putty & spray up paint works	\$	1,200.00 800.
3	To check wiring	\$	50.00 30
4	To remove reverse sensor	\$	100.00 50
5	To remove rear camera	\$	100.00 50
6	To remove video camera	\$	100.00 50
7	To remove upholstery	\$	150.00 80
8	To transfer tailgate fittings	\$	150.00 80
9	To remove tailgate glass	\$	180.00 120
10	To remove exhaust pipe	\$	150.00 x.
Total Labour			\$ 3,380.00

RE : ESTIMATE FOR ACCIDENT REPAIR SMC4157K (HONDA VEZEL)

Grand Total

\$ 11,817.92

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 7740 .96

L/s: 6.2K.

06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: