HSIAU TONY

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/67467158 Fax No: 67458520

Tax Reg No: 200006262D

Not Arthornal 10/5/22 2/5412,000 12days.

**VEHICLE No: SBL 75Y** 

1PC	REAR WINDSCREEN MOULDING	Nec		\$110.20
1PC	TAILGATE	Boolyno	997-30	\$1,099.20
1PC	TAILGATE 'VEZEL' EMBLEM	nec		\$66.80
1PC	TAILGATE 'H' LOGO	nu		\$45.00
1PC	TAILGATE OUTER HANDLE GARNISH	cre	312.00	\$450.00
2PCS	TAILGATE REFLECTORS @\$386.20	che	325.10×2=610.50	
1PC	TAILGATE INNER LOCK	suf	180.20	\$199.80
1PC	TAILGATE LOCK STRIKER	ni	40.00	\$66.00 ×
1PC	TAILGATE INNER TRIM BOARD	5.2	788.80	\$435.00
1SET	TAILGATE INNER TRIM BOARD CLIPS	s 1u		\$50.00
1PC	TAILGATE REAR WIPER MOTOR	su		\$645.20 X
1PC	TAILGATE WEATHERSTRIP	121	162.30	\$288.00
1PC	REAR BUMPER	11	762-30	\$980.00
2PCS	REAR BUMPER SIDES @\$235.10	DIS /wage	1	\$470.20
2PCS	REAR BUMPER REFLECTORS @\$151			\$302.00 126
1PC	REAR BUMPER UNDER COVER	から	311.70	\$541.00
1SET	REAR BUMPER UNDER COVER CLIPS			\$50.00
1SET	REAR BUMPER CLIPS	nu		\$50.00
1PC	REAR END PANEL	3008.80	5-17.30	\$665.20
1PC	REAR END PANEL TOP GARNISH	Del	122.60	\$341.10
2PCS	TAILLAMPS @\$650.00	Chei	482 x 2 = 964	\$1,300.00
2PCS	TAILLAMP HOUSING PANELS @\$350		ols w 58%	\$700.00 12 6
1PC	REAR BUZZLE SENSOR	(ng		\$98.00
1PC	REAR ANTENNA SENSOR	chei	/-	\$188.20
2PCS	REAR FENDERS @\$1090.00		s suc 971.10	\$2,180.00 100
2PCS	REAR FENDER OUTER PROTECTORS		1/25 245425 490	\$760.00
2PCS	REAR FENDER INNER TRIM BOARDS	@\$395.00 Le	/DUS 381 x 2= 762	\$790.00
1PC	REAR FENDER UNDER TRIM O/S	To. A	186.50	\$336.00
1PC	REAR WHEEL HOUSING PANEL O/S	Rull	2	\$909.20 >
1PC	REAR FLOOR PANEL	crumpul /3	suc 1025-30	\$1,280.00
1PC	REAR FLOOR PANEL SIDE PANEL O/S		211.50	\$455.00
1PC	REAR FLOOR PANEL TOP BOARD	norsel	316.00	\$522.00
1PC	REAR FLOOR PANEL TOOLS SPONGE	Torn	450-50	\$785.00
2PCS	REAR EXHAUST MOUNTINGS @\$60.0			\$120.00
1PC	REAR EXHAUST	suf	645	\$765.00
1PC	CENTRE EXHAUST PIPE	sut	1	\$1,055.20
1PC	REAR EXHAUST HEAT SHIELD	But	202 1015	\$168.00
				\$20,038.70

1PC	REAR WINDSCREEN SEALANT	1 ec		\$50.00 40	
1PC	REAR WINDSCREEN INNER SEAL	u		\$50.00 40	
1PC	REAR END PANEL SEALANT	er,		\$50.00	
1SET	REAR BUMPER REVERSE SENSOR	Charles		\$280.00 220	
1SET	REAR REVERSE CAMERA	11		\$450.00 ×	
1SET	REAR FLOOR PANEL INSULATOR	17		\$120.00 X	
1PC	REAR LICENCE PLATE			\$50.00 40	
	TO CEHCK WIRING			\$50.00 30	
	TO DISMANTLE & REPLACED REVERSE SENSOR			\$80.00 50	
	TO DISMANTLE & REFX REAR WINDSCR	EEN		\$150.00 120	
	TO TRANSFER TAILGATE MECHANISM			\$100.00 6 0	
	TO DISMANTLE & REFIX CUSHION UPHO	OLSTERY		\$120.00 80	
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM			\$180.00	
	TO DISMANTLE & REFIX REAR EXHAUST TO SPRAY RUST PROOFING		\$180.00 /00		
	TO DISMANTLE & REFIX REAR UNDER C	ARRIAGE	11	\$280.00 X	
	TO CONDUCT WHEEL ALIGNMENT			\$100.00 60	
	TO DISMANTLE & REFIX FUEL TANK			\$100.00 60	
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$2,800.00 2220		
	TO PUTTY & SPRAY PAINTING			\$1,800.00   3,22	
		TO	TAL \$2	27,128.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

1510264 5-1012064 5-1012064 [510264 [510264