



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM22004348/Uea3q2 Date: 20/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMT 6184D	Veh. Inspected	SJQ 9872H
	Policy No.	GA587256	Coverage (\$)	0.00
	Claim No.	S2M040F5	Excess (\$)	0.00
	Assign From		Assign Date	10/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PREVIA 8 SEATER (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTEGD52M20A013483	Colour	SILVER
	Odometer	411690 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50Z R17	HABILEAD	6 mm
	L/H Front Tyre	225/50Z R17	HABILEAD	6 mm
	R/H Rear Tyre	225/50Z R17	HABILEAD	6 mm
	L/H Rear Tyre	225/50Z R17	HABILEAD	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/05/2022	Inspection Date	10/05/2022
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	