



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG			Ref: CC4/ASM22004350/Apa3q2 Date: 03/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 6381E	Veh. Inspected	SJJ 3106M
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M040DJ	Excess (\$)	0.00
	Assign From		Assign Date	10/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALLION	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	NZT2603021845	Colour	BLACK
	Odometer	316368 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/05/2022	Inspection Date	11/05/2022
	Survey held at	AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	