

**AUTO UNITED SG PTE LTD**

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel. 6844 1184

TP A x A.

Xiao Tong.

Page No. 1

Vehicle No. SJJ3106M TOYOTA ALLION

NZT 2603021845

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
2	FRONT HEADLAMP RH & LH @ \$1025.2	Crushed	2050.40	1630
1	FRONT BONNET	new	810.50	+
1	FRONT BONNET LOCK	new	93.50	+
1	FRONT BONNET INSULATOR	new	295.50	+
1	FRONT BONNET LOGO	new	75.00	+
2	FRONT BONNET HINGE RH @ LH @ \$190.60	new	381.20	+
1	FRONT BUMPER	Deformed	1355.80	1080
2	FRONT BUMPER SIDE RETAINER RH & LH @ \$127.6	new	255.20	170.
1	FRONT BUMPER UPPER GRILLE	Crushed	652.20	349.
1	FRONT BUMPER LOWER GRILLE	Crushed	180.50	✓
1	FRONT BUMPER INNER SPONGE	Crushed	101.20	✓
1	FRONT BUMPER REINFORCEMENT	Dented	541.60	322.
2	FRONT LOWER BUMPER LED LAMP RH & LH @ \$120.00	new	240.00	+
1	FRONT SUPPORT PANEL	new	788.50	+
2	FRONT FOGLAMP GARNISH RH & LH @ \$330.60	3 new	661.20	+
2	FRONT FENDER RH & LH @ \$715.20		1430.40	+
1	FRONT WIPER TANK	new	101.70	+
1	FRONT CONDENSER	Dented	1189.50	✓
1	FRONT RADIATOR	new	1225.50	+
1	REAR BOOTLID	Buckled	1092.00	✓
1	REAR BOOTLID LOGO	new	75.00	✓
1	REAR BOOTLID TOP LOCK	Damaged	395.00	✓
1	REAR BOOTLID LOWER LOCK	new	48.00	+
1	REAR BOOTLID WEATHERSTRIP	at	230.80	✓
1	REAR BOOTLID CHROME	Crushed	223.20	✓
2	REAR TAILLAMP RH & LH @ \$879.5	Crushed	1759.00	680
2	REAR TAILLAMP BRACKET RH & LH @ \$111.6	new new	223.20	+
2	REAR FENDER RH & LH @ \$979.50	Repair	1959.00	+
1	REAR BUMPER	Deformed	1490.00	1080
2	REAR BUMPER SIDE RETAINER RH & LH @ \$190.80	new	381.60	110.
2	REAR BUMPER SIDE BRACKET RH & LH @ \$147.20	Dented	294.40	125.
2	REAR BUMPER REFLECTOR RH & LH @ \$191.80	RH crushed	383.60	191.80
1	REAR END PANEL	Dented	927.90	598
1	REAR END PANEL TOP GARNISH	Deformed	211.10	✓
1	REAR SPARE TYRE PANEL	Back Buckled	921.30	✓
1	REAR SPARE TYRE PANEL SPONGE	Top Cover Deformed	306.00	✓
1	REAR SPARE TYRE INNER SPONGE	new new	227.60	+
			23578.10	
		less	25% 5894.53	25%
			17683.58	
	SPECIAL NETT ITEMS			
1 SET	FRONT BUMPER CLIPS	3 new	100.00	30
1 SET	FRONT GRILLE CLIPS		100.00	20
1 SET	FRONT INNER PROTECTOR GARNISH CLIPS	new	100.00	+
1	FRONT CAR PLATE WITH COVER	new new	70.00	+
1	REAR BUMPER CLIPS	new	100.00	30

1	REAR CAR PLATE WITH COVER	<i>Not in</i>	70.00	<i>x</i>
1	REAR END PANEL SEALANT	<i>NA</i>	100.00	<i>60</i>
1 SET	REVERSE SENSOR	<i>Damaged</i>	280.00	<i>200</i>
Total Parts			18503.58	

340



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel. 6844 1184

Page No. 2

Vehicle No. SJJ3106M TOYOTA ALLION

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	2200.00 1300	1800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	2000.00 1800	
3	To remove and refix wiring at damaged areas	150.00 60	
4	To perform anti rust treatment on affected areas	200.00 100	
5	To conduct water seepage test	150.00 x.	
6	To remove and refix cushion and inner trim	180.00 100	3020
7	To remove and replace <i>reverse sensor</i>	250.00 x.50	3710
Labour Total :		5130.00	
TOTAL (PARTS & LABOUR):		22813.58	

Adrian Lim
H/S 11/05/22

12 Days.

total: 12486.05
H/S: 9/10/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

10/2