

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: BMW 125i

Engine/Chassis No.: WBAUC32020VH93909


Date of accident:

Damaged area: O/S Front

Date: 11/05/2022

Claim Type: TP

VRN: SMF3266U



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Headlamp o/s	1	\$ 1,982.90	\$ 1,982.90
2	Headlamp lower bracket o/s	1	\$ 76.80	\$ 76.80
3	Front bumper <i>1150</i>	<i>Bur/red</i> 1	\$ 1,482.70	\$ 1,482.70
4	Front bumper side retainer <i>108</i>	<i>o/s</i> 2	\$ 144.00	\$ 288.00
5	Front fender cowling o/s	1	\$ 310.60	\$ 310.60
6	Front fender o/s	1	\$ 1,041.20	\$ 1,041.20
7	Front wheel carrier o/s <i>641</i>	1	\$ 736.10	\$ 736.10
8	Front control arm o/s	1	\$ 413.50	\$ 413.50
9	Front endlink o/s	1	\$ 174.20	\$ 174.20
10	Front shock absorber o/s <i>486</i>	1	\$ 538.60	\$ 538.60
11	Front shock absorber top mount o/s	1	\$ 97.30	\$ 97.30
12	Front wheel bearing o/s	1	\$ 187.40	\$ 187.40
13	Front lower arm o/s	1	\$ 325.90	\$ 325.90
Subtotal				\$ 7,655.20
List discount				5.00%
Total				\$ 7,272.44

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips <i>na</i>	12	\$ 5.50	\$ 66.00
2	Front sports wheel o/s <i>Del</i>	1	\$ 550.00	\$ 550.00
3	Front tyre o/s <i>na</i>	1	\$ 380.00	\$ 380.00
4	Sundries <i>na</i>	1	\$ 50.00	\$ 50.00
Total				\$ 1,046.00

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
3	To remove and replace o/s front tyre & rim. To perform tyre balancing.	0.25	\$ 50.00
4	To remove and refit o/s front undercarriage for replacement of parts.	1	\$ 200.00
5	To conduct computerized wheel alignment.	0.5	\$ 100.00
6	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,700.00

4001
156
201
1801
601
4001
X

Estimate Grand Total	\$ 11,018.44
----------------------	--------------

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Subsequently item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 - Acknowledged by Repairer
 Signature: