

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM M 54794

at Workshop m/s C & C US,

of _____

Insured: SM W 4350M

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 70k.

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 37693

Date / Time Action / Instruction Dep 9k.

Veh No: SM M 54794 Yr Regn: 03/07/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: KIA Cerato SX cc 1591

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 198570 T/Radio: Insured / Std / NI / NA

Eng/No: 198570

C/No: KNAF3416mk 5049435

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 08/05/22 D.O.I. 12/05/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 848F

Vehicle Details

Vehicle No.: SMM5479Y

Vehicle to be Exported: No

Intended Deregistration Date: 12 May 2022

Vehicle Make: KIA

Vehicle Model: CERATO 1.6(A) SX

Primary Colour: Grey

Manufacturing Year: 2019

Engine No.: G4FGKH743019

Chassis No.: KNAF3416MK5049435

Maximum Power Output: 93.8 kW (125 bhp)

Open Market Value: \$18,659.00

Original Registration Date: 03 Jul 2019

First Registration Date: 03 Jul 2019

Transfer Count: 0

Actual ARF Paid: \$18,659.00 9329

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Jul 2029

PARF Rebate Amount: \$13,994.00

Intended COE Rebate Details

COE Expiry Date: 02 Jul 2029

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$33,199.00

COE Rebate Amount: \$23,699.00

Total Rebate Amount: \$37,693.00

The information contained herein is correct as at 12 May 2022

OK



CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE



Movement that inspires

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name LCV10428/Mr Dedi Supiadi Herry Reg No/Reg Date SMM5479Y / 03/07/2019 Date In/Mileage 09/05/2022/ 197762 Chassis No KNAF3416MK5049435 Engine No G4FGKH743019 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim ABT / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	10/05/2022/ 08:56	DS	218 / Mars Ler	29702

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00 ✓
S MIPNT88088 TO TRANSFER RHR DOOR COMPONENTS AND MECHANISMS PARTS				640.00
S MIPNT88088 TO REPLACE RHR DOOR PANEL,ETC -TO REPAIR RHS SIDE SILL STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT AFFECTED AREAS				1280.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW PANEL				200.00
S MIPNT98088 SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS				1650.00
M KS 77004 M6 000 RH REAR DOOR PANEL A	1.00	1445.00	0.00	1445.00
M KS 83220 M6 010 W/STRIP ASSY-RR DR B	1.00	75.00	0.00	75.00
M KS 77521 M6 000 BLACK TAPE-RR DR FR,	1.00	13.00	0.00	13.00
M KS 77523 M6 000 BLACK TAPE-RR DR FRA	1.00	8.00	0.00	8.00

Z NOTES

ACCIDENT ON 08/05/2022 ALONG SULTAN ISKANDAR CIQ JB TOWARDS SG
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP # SMW4350M TP INS : CHINA TAIPING

Not Allowed
LHR

Take photo before repair

12/5/22

2 days

9/17/22

Confirm & accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Parts	1,541.00
Labour	0.00
Standard Menu	0.00
Specialist Job	4,020.00
Others (Lub,etc)	0.00
Sundry	0.00
Total (w/o GST)	5,561.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

