



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004362/Kqy3n2	
			Date: 02/06/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SKZ 8455B	Veh. Inspected	GBA 27U
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201497/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	10/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTFHT02P200247712	Colour	WHITE
	Odometer	132882 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	YOKOHAMA	8 mm
	L/H Front Tyre	195 R15X8	YOKOHAMA	8 mm
	R/H Rear Tyre	195 R15X8	YOKOHAMA	8 mm
	L/H Rear Tyre	195 R15X8	YOKOHAMA	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	30/04/2022	Inspection Date	10/05/2022
	Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	