

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD555A**AAD2205-034***Not Authorised
L/Rp \$ 3850.*

Vehicle No.:

09 MAY 2022

Chassis No.:

SHD555A

VF1ABL15AUC282637

UEN No:

200303878K

Vehicle Make:

RENAULT

Vehicle Model:

091 2022

LATITUDE

Date of Accident :

06/05/2022

Third Party Insurer :

SNB7953C/AIG

Date of Registration :

04/02/2016

PART**LIST**

1 BUMPER COVER REAR
 1 BUMPER LOWER REAR
 1 BUMPER BRACKET CTR REAR
 1 BUMPER BRACKET SIDE RH REAR
 1 BUMPER RETAINER RH REAR
 1 BUMPER BRACKET SIDE LH REAR
 1 BUMPER RETAINER LH REAR
 1 FENDER PANEL REAR LH
 1 BUMPER BEAM REAR
 1 BUMPER BEAM BRACKET LH REAR
 1 BUMPER BEAM BRACKET RH REAR
 1 OUTER PANEL REAR (End Panel)
 1 OUTER PANEL REAR (End Panel)TRIM
 1 BOOT REAR
 1 BOOT LOCK
 1 BOOT LOCK CATCH
 1 BOOT FINISHER
 1 BOOT WEATHERSTRIP
 1 BOOT STRUT LH
 1 BOOT STRUT RH
 1 BOOT HINGE LH
 1 BOOT HINGE RH
 1 BOOT BADGE 'RENAULT'
 1 BOOT BADGE
 1 TAILLAMP RH

\$	<i>Per 1cm</i>	561.70	✓
\$	<i>Per</i>	411.90	✓
\$	<i>Per</i>	98.10	✓
\$	<i>Per</i>	82.10	X
\$	<i>Per</i>	59.80	X
\$	<i>Per</i>	80.80	✓
\$	<i>Per</i>	54.20	X
\$	<i>Per</i>	1,933.20	X
\$	<i>Per</i>	547.80	✓
\$	<i>Per</i>	114.50	X
\$	<i>Per</i>	114.50	✓
\$	<i>Per</i>	745.80	X
\$	<i>Per</i>	404.56	X
\$	<i>Per</i>	1,677.20	✓
\$	<i>Per</i>	246.60	X
\$	<i>Per</i>	41.70	✓
\$	<i>Per</i>	344.70	X
\$	<i>Per</i>	178.20	X
\$	<i>Per</i>	145.10	X
\$	<i>Per</i>	145.10	X
\$	<i>Per</i>	254.20	X
\$	<i>Per</i>	254.20	✓
\$	<i>Per</i>	82.40	✓
\$	<i>Per</i>	95.80	✓
\$	<i>Per</i>	401.40	X
\$		9,075.56	

Trans-cab Auto Services Pte Ltd

AAD2205-034

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD555A

10%	\$	907.56
	\$	8,168.00

Special Nett

1SET PARKING AID	\$	Short	700.00	400sat
1SET REAR BUMPER CLIP	\$	nn	66.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
1 REAR BOOT STICKER 'Trans-cab'	\$	nn	80.00	30sn
1 REAR BOOT STICKER '6555-3333'	\$	nn	80.00	30sn
1 LICENSE PLATE WITH HOLDER REAR	\$	sn	120.00	X
2 WINDSCREEN SEALANT	\$	nn	150.00	X
1 WINDSCREEN MOULDING	\$	nn	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	X
TOTAL	\$		1,652.00	
TOTAL PARTS	\$		9,820.00	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00	X
Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	450
To Rust-Proofing Of The Affected Areas.	\$		170.00	30
To reinstall rear bumper parking sensor.	\$		170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2205-034

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD555A

To repair and realign rear exhaust pipe. \$ *nn* 170.00 X

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. \$ *h* 170.00 X

To transfer of rear end panel fittings, attachment and perform water seepage test. \$ *h* 170.00 X

To transfer of rear windscreen fittings and conduct water seepage test. \$ *h* 170.00 X

To check steering geometry and computer wheel alignment \$ *h* 220.00 X

To Check Electrical Lighting Concerned. \$ 170.00 *15/*

TOTAL \$ 7,880.00

Over All Total \$ 25,868.01

(LUMP SUM)

Repair Days

20 DAYS

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: