

ASS. REC. BY:

REF:

EQ / 22004365 / kgv3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. DM 2241000726/MT

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S11D 5447X Yr Regn: 10, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Prius c.c. 1798Colour M.P White / Red A/C: Insured / Std / NI / NASp.Reading 415764 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKCB 31-U 2030 73724Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or 195/65R15

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 9 mmL/Bal. 7 mm L/Bal. 9 mmD.O.A. 8/5/22 D.O.I. 10/5/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/5 11:50 @ 4400. Cahu (Red & 11668.98, 737.)

Date/Time, File Pass to?

☐ : Prel. Report

1) 14/06 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.T. (\$

TP
4400

Not Notarised
 11 Sep 8 4400h

AAD2205-042.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5447X

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 MAY 2022

SHD5447X

JTDKB3FU203073724

200303878K

TOYOTA

PRIUS

08/05/2022

GBD8143Z/EQ

26/10/2018

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	1,300.70 ✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	193.50 X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	390.60 ✓
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	110.60 X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	97.50 X
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	13.30 ✓
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	43.50 ✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	26.30 ✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$	926.00 ✓
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	238.30 ✓
1	WEATHERSTRIP, FRONT DOOR, RH	\$	231.30 X
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	1,294.90 ✓
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	97.40 X
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	193.50 X
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	87.10 X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	98.90 X
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	21.90 ✓
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	34.90 ✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	15.40 ✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	926.00 X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	206.70 X
1	WEATHERSTRIP, REAR DOOR, RH	\$	180.10 ✓
1	COVER, REAR BUMPER	\$	442.60 X
1	SEAL, REAR BUMPER SIDE, RH	\$	88.50 X
1	FILLER, REAR BUMPER EXTENSION, RH	\$	123.70 X
1	PANEL SUB-ASSY, QUARTER, RH	\$	871.50 X
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80 X

Trans-cab Auto Services Pte Ltd**AAD2205-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5447X

- 1 MIRROR ASSY, OUTER REAR VIEW, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL RH
- 1 RIM

\$	<i>Sm</i>	1,436.60	X
\$	<i>n</i>	977.80	X
\$	<i>Sm</i>	206.70	X
\$	<i>na</i>	54.60	✓
\$	<i>Sm</i>	1,900.10	X
TOTAL	\$	13,425.30	
25%	\$	3,356.33	
	\$	10,068.98	

Special Nett

- 1 CLIP(FOR FRONT DOOR TRIM BOARD)
- 1 CLIP(FOR REAR DOOR TRIM BOARD)
- 1 REAR DOOR STICKER "6555-3333"
- 1 FRT DOOR STICKER 'TRANSCAB'
- 1 REAR DOOR ADVERTISEMENT
- 1 FRONT DOOR ADVERTISEMENT
- 1 TYRE
- 1 FENDER LINER CLIP
- 1 FRT BUMPER CLIP

\$	<i>na</i>	65.00	X
\$	<i>na</i>	65.00	X
\$	<i>na</i>	100.00	<i>60na</i>
\$	<i>na</i>	100.00	<i>60na</i>
\$	<i>na</i>	200.00	<i>100na</i>
\$	<i>na</i>	200.00	<i>100na</i>
\$	<i>SLC</i>	350.00	X
\$	<i>na</i>	65.00	X
\$	<i>na</i>	65.00	X
TOTAL	\$	1,210.00	

TOTAL PARTS \$ 11,278.98**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	<i>601</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>11001</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	<i>6001</i>

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5447XTo check steering geometry and computer wheel alignment \$ *nn* 220.00 XTo transfer of rear fender panel fittings, attachment and perform water seepage test. \$ *nn* 170.00 X**TOTAL** \$ 4,790.00**Over All Total** \$ 16,068.98**(PART-BY-PART) Repair Days***20 Days**4 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD5447X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B49643
Chassis No.:	JTDKB3FU203073724
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	26 Oct 2018
First Registration Date:	26 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2026
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	25 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,228.00
COE Rebate Amount:	\$13,506.00
Total Rebate Amount:	\$24,191.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 May 2022

OK