



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22004368/Any3q2 Date: 18/08/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 4838U	Veh. Inspected	GBJ 4293T	
Policy No.		Coverage (\$)	0.00	
Claim No.	2022 22004803SL	Excess (\$)	0.00	
Assign From	SHANTI	Assign Date	10/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 1	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFAT35Y50K212576	Colour	WHITE	
Odometer	68088 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	TRIANGLE	6 mm	
L/H Front Tyre	195 R15C	TRIANGLE	6 mm	
R/H Rear Tyre	155 R12C	APLUS	6 mm	
L/H Rear Tyre	155 R12C	APLUS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2022	Inspection Date	11/05/2022	
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	