

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address                                                                                                              | Owner Name & Vehicle Info                                                                                                                                                                                                                                |
|-------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| ALOYSIUS MICHAEL MOK KOK JUN (MO GUOJIN)<br>17 ANCHORVALE CRESCENT<br>#13-15<br>SINGAPORE 544652<br><br>Contact No Mobile: 98440066 | Cust No/Name /ALOYSIUS MICHAEL MOK KOK JUN (M<br>Reg No/Reg Date SMQ6236D / 27/11/201<br>Date In/Mileage / 0<br>Chassis No GF7W0602135<br>Engine No 4J11BL0082<br>Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994)<br>Colour/Trim W01 WHITE PEARL / BK BLACK |

| Account No                                                 | Terms | Date/Time Printed | CSE | Operator          | WIP No |            |       |             |
|------------------------------------------------------------|-------|-------------------|-----|-------------------|--------|------------|-------|-------------|
| CSM00041                                                   | Cash  | 09/05/2022/ 17:53 | TLK | 282 / Kevin Leong | 23138  |            |       |             |
| Description of Goods / Services                            |       |                   |     |                   | Qty    | Unit Price | Disc% | Amount      |
| E PNT88000                                                 |       |                   |     |                   |        |            |       | 640 1280.00 |
| REPLACE REAR BUMPER PANEL & AFFECTED AREA                  |       |                   |     |                   |        |            |       |             |
| E PNT98000                                                 |       |                   |     |                   |        |            |       | 550 1650.00 |
| PAINT WORK ON REAR BUMPER & REAR LH FENDER                 |       |                   |     |                   |        |            |       |             |
| E PNT88000                                                 |       |                   |     |                   |        |            |       | 129 150.00  |
| REMOVE & REPLACE BODY KIT                                  |       |                   |     |                   |        |            |       |             |
| E PNT88000                                                 |       |                   |     |                   |        |            |       | 80 150.00   |
| REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR |       |                   |     |                   |        |            |       |             |
| M SUNDRY                                                   |       |                   |     |                   |        |            |       | X 80.00     |
| PERFORM RUST PREVENTION                                    |       |                   |     |                   |        |            |       |             |
| M SUNDRY                                                   |       |                   |     |                   |        |            |       | X 50.00     |
| TO APPLY SEALANT ON AFFECTED AREA                          |       |                   |     |                   |        |            |       |             |
| A 54900099                                                 |       |                   |     |                   |        |            |       | 100 150.00  |
| CHECK WIRING & CHASSIS ELECTRICAL SYSTEM                   |       |                   |     |                   |        |            |       |             |
| A 10028901                                                 |       |                   |     |                   |        |            |       | 280.00      |
| TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM |       |                   |     |                   |        |            |       |             |
| M SUNDRY                                                   |       |                   |     |                   |        |            |       | 20 50.00    |
| SUNDRIES                                                   |       |                   |     |                   |        |            |       |             |
| M REFLECTOR, TAIL LAMP, LH                                 |       |                   |     |                   | 1.00   | 100.00     | 00.00 | 100.00      |
| M FACE, RR BUMPER                                          |       |                   |     |                   | 1.00   | 1119.00    | 00.00 | 1119.00     |
| M BRKT, R/BMPR FACE SIDE, LH                               |       |                   |     |                   | 1.00   | 27.00      | 00.00 | 27.00       |
| M EXTENSION, RR BUMPER                                     |       |                   |     |                   | 1.00   | 358.00     | 00.00 | 358.00      |
| M BODY KIT, OUTLANDER                                      |       |                   |     |                   | 1.00   | 1554.00    | 00.00 | 1554.00     |

Estimate

Steve (LKK)  
16/6/22, 3:30pm

Whe PL  
3 days  
P/P  
My BL y

cut (1 set) take photo whole set body kit

LKK Auto Consultants hence notify

Steve (LKK)  
16/6/22, 3:30pm

Wm R  
3 days  
P/P  
by BLG

Confirm & accepted by LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on Net 6,998.00 489.86  
 Total Payable 7,487.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.