



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004371/Avy3e2	
			Date: 17/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 7263S	Veh. Inspected	SMR 7288S
	Policy No.	D22MTPCVE000970	Coverage (\$)	0.00
	Claim No.	CMTD2201605/THE	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	10/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VELLFIRE	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	AYH300083076	Colour	BLACK
	Odometer	182898 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R17	TOURADOR	6 mm
	L/H Front Tyre	225/60 R17	TOURADOR	6 mm
	R/H Rear Tyre	225/60 R17	TOURADOR	6 mm
	L/H Rear Tyre	225/60 R17	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/05/2022	Inspection Date	10/05/2022
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	