

HUA MENG SPRAY PAINTING WORKSHOP

LKK Auto Consultants hence notify

the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

YONG WEI PHENG

BLK 894B WOODLANDS DRIVE 50

#05-43

S 732894

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

AYH 300083076

Vehicle No : SMR 7288 S
Make/Model : TOYOTA VELLFIRE
Accident date : 09.05.2022

TP Sampo
Veron.

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Front bumper Torn	1	\$ 2503.50
2	Front bumper side holder @ \$205.80 R + and	2	\$ 411.60
3	Front RH side grille New	1	\$ 685.30
4	Front RH headlamp Crushed	1	\$ 9178.10
5	Front RH fender Dented	1	\$ 1461.00
6	Front RH fender inner shield Re-hd	1	\$ 686.10
7	Front RH fender Hybrid emblem New	1	\$ 145.50
8	Front RH quarter glass Lt	1	\$ 698.30
9	Front RH quarter glass rubber New	1	\$ 329.40
10	Front RH quarter glass moulding Replaced	1	\$ 338.30
11	Front RH door Dented	1	\$ 3337.80
12	Front RH door side mirror cover Dmd	1	\$ 205.30
13	Front RH door side mirror Dmd	1	\$ 2365.30
14	Front RH door side mirror housing	1	\$ 338.30
15	Front RH door side mirror signal lamp New	1	\$ 877.30
16	Front RH knuckle arm Dmd	1	\$ 686.00
17	Front RH knuckle arm bearing Dented	1	\$ 686.20
18	Front RH lower arm New	1	\$ 24933.30
			\$ 13840.10
			Less 25% Disc \$ 6233.33
			10380.07 Total \$ 18699.98

Special Nett Items

1	Front RH fender inner shield clips (1 set) New	1	\$ 60.00
2	Front RH sport rim Lt	1	\$ 2781.10
3	Front RH tyre New	1	\$ 380.00
4	Front RH sensor New	1	\$ 757.30
			Total \$ 3978.40

5 Front RH Door Visor nec 120.80
6 Front RH Quarter Glass Solar Film 200.120

Labour Cost

1	To check wheel alignment	\$ 100.00
2	Remove & reinstall front RH suspension	\$ 400.00
3	Remove & reinstall front sensor	\$ 150.00
4	Remove, replace & repair consistent to the accident	\$ 1200.00
5	Respray painting	\$ 1200.00
6	Tuff kote	\$ 100.00
		Total \$ 3150.00

7 Transfer door fittings

Total 13750.07

Grand Total

\$ 25828.38

152.80.

HK

HS: HK

06 Days