



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22004372/Aqy3e2 Date: 01/09/2022 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 6313S	Veh. Inspected	SLG 9215J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/05/22/2019	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	10/05/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ C180 COUPE	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD2053402F346668	Colour	BLACK	
Odometer	92391 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/05/2022	Inspection Date	10/05/2022	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	