

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TPS MRT.
Xiao Chan.

LEE KOK WEI
BLK 329 YISHUN RING ROAD #08-1414
SINGAPORE 760329

TAX INVOICE

Repair Code : CLM17192

Date in : 09/05/2022

Vehicle Num. : SLG9215J

Model : MERCEDES BENZ C180 COUPE (R17 LED)

Chassis/Eng# : WDD2053402F346668/27491030627244

Contact : 88215278

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Repr</i>	1	1885.00	+ 1,885.00
FRONT BUMPER INNER SPONGE <i>new</i>	1	180.00	+ 180.00
FRONT BUMPER PARKING SENSOR <i>1 piece long d</i>	2	195.00	195 390.00
FRONT BUMPER PARKING SENSOR 'O' RING <i>new</i>	2	12.00	✓ 24.00
FRONT BUMPER RIVET <i>3 new</i>	20	9.00	+ 180.00
FRONT BUMPER SIDE BRACKET <i>3509</i>	1	115.00	+ 115.00
FRONT BUMPER SIDE RETAINER L/R <i>3158-10</i>	2	25.00	+ 50.00
FRONT LH FENDER <i>Repr</i>	1	1015.00	+ 1,015.00
FRONT LH FENDER INNER SHIELD (FRONT) <i>new</i>	1	145.00	+ 145.00
FRONT LH HEADLAMP <i>cracked</i>	1	3679.00	3679.00 3292.00
FRONT LH WHEEL RIM <i>lit</i>	1	1550.00	1550.00 1250.00
Subtotal before discount			9,213.00
Percentage discount 10%			921.30
Sub-total 1			8,291.70
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	+ 50.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	+ 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LEE KOK WEI
BLK 329 YISHUN RING ROAD #08-1414
SINGAPORE 760329

Contact : 88215278

TAX INVOICE

Repair Code : CLM17192

Date in : 09/05/2022

Vehicle Num. : SLG9215J

Model : MERCEDES BENZ C180 COUPE (R17 LED)

Chassis/Eng# : WDD2053402F346668/27491030627244

Subtotal before discount	100.00
Percentage discount 0%	0.00
Sub-total 2	100.00
Parts-total	8,391.70

LABOUR

- To reset system after repair works
- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To road test driving, check and resetting wheel alignments system.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

X 250.00
✓ 60.00
1020
80- 100.00
500 700.00
350 600.00
30 50.00

1,760.00

10,151.70

*** This is a computer-generated document which requires no signature.***

page 2

Adrian L
K/S 10/05/22
0 ADP2

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5278.10
L/S: A.K.

A.K.
040mp