



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22001802/Vqy3e2-1	
			Date: 14/06/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5681X	Veh. Inspected	SMZ 1976L
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/02/22/2064	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	10/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD2050402R104494	Colour	GREY
	Odometer	85575 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	PIRELLI	6 mm
	L/H Front Tyre	225/50 R17	PIRELLI	6 mm
	R/H Rear Tyre	225/50 R17	PIRELLI	6 mm
	L/H Rear Tyre	225/50 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/02/2022	Inspection Date	25/02/2022
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	