



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|--|----------------------------|------------|
| ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 | | | Ref: CS/AIS22004375/Eqy3e2 | |
| | | | Date: 02/09/2022 | |
| | | | Code: AIS | |
| 1. Policy Particulars :- OWN DAMAGE | | | | |
| | Insured Veh. | | Veh. Inspected | SMZ 3605U |
| | Policy No. | SP2001457397 | Coverage (\$) | 0.00 |
| | Claim No. | 2022 22004793FR | Excess (\$) | 1,000.00 |
| | Assign From | SHANTI | Assign Date | 10/05/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | B.M.W. 218I | c.c | 1499 |
| | Engine No. | HIDDEN | Year of Reg. | 2021 |
| | Chassis No. | WBA12AK0307H64353 | Colour | RED |
| | Odometer | 12617 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 225/40 R18 | BRIDGESTONE | 4 mm |
| | L/H Front Tyre | 225/40 R18 | BRIDGESTONE | 4 mm |
| | R/H Rear Tyre | 225/40 R18 | BRIDGESTONE | 4 mm |
| | L/H Rear Tyre | 225/40 R18 | BRIDGESTONE | 4 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 07/05/2022 | Inspection Date | 11/05/2022 |
| | Survey held at | PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941 | | |
| 5a. Remarks | | | | |
| | A)THE MARKET VALUE IS S\$154,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 8 Working Days | |