per Dealer

## **Performance Motors Limited**

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Bime Darby Performance Centre Bingapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 61749

Date Estimated

: 10/05/2022

WBA12AK0307H64353

Prepared By

: Inthiran A/L Thurasamy

REGN. NO. SMZ3605U CHASSIS NO.

REGN. DATE 23/04/2021 MODEL

218i Gran Coupe

MILEAGE

Page No. : 2 of 5

VALUE DESCRIPTION PRIC 281.75 281.75 LH TIE ROD / (/)
ALLOY RIM 8JX18 DOUBLE SPK 819M / LH TIE ROD 1,310.85 1,310.85 1 32.50 19.80 🗸 10 3.25 3.3 **BUMP STOP** 37.85 38.45 🗸 COVER WINDSHIELD TOP 37.85 - PC WINDSCREEN GREEN RAIN/LIGHT/CONDENS / PR 826.50 838.90 🗸 826.50 26.15 26.15 (DG) CLEANER R1 (100ML) / NC 27.85 27.85 (DG/SL)ADHESIVE PRIMER VP 206 (30ML / NC

Total Parts

9,915.85

Steve CLKK) Exact- 2
11/5/97, 12.79 P/P

OD-MAL EXAM-? PIP MBIL 19 8 YS



Labour 1 : 6,446.50
Parts : 9,915.85
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 1,145.36

Grand Total

17,507.71

<sup>&#</sup>x27;THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

BNW Dealer

## Performance Motors Limited

A Sime Darby Motore Company Co. Reg. No. 197401559W GST Reg. No M2-0020061-X Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Eampong Arang Road East Coast Centre Singapore #38180 Fax. 63449773 118, Alexandra Road Sime Darby Business Centre Singapore 189944 Fax. 64796601 (AfterSales) 64796624 (Motorrad)



## GST REG. NO : M2 - 0020081 - X

ESTI	M	Α	$\mathbf{T}$	$\mathbf{E}$
------	---	---	--------------	--------------

Estimate No. : b1 61749  Date Estimated : 10/05/2022  Prepared By : Inthiran A/L Thurasamy	Page No. : 1 of 5				
- ESTIMATE REPAIR FOR - Saraswathi D/o Ramachandran 2 BISHAN ST 25 #02-08  SINGAPORE 573973  - ACCOUNT - 224093 Allianz Insurance Singapore Pte Ltd 79 Robinson Road #09-01 Singapore 068897					
REGN. NO. CHASSIS NO. REGN. DA SMZ3605U WBA12AK0307H64353 23/04/20	10075				
To remove and install front suspension for inspection and replace damaged parts.					
To replace tyre and wheel rim including balancing. (1x). $90 \checkmark 94.$ To check steering geometry and conduct wheel alignment in $1009 \checkmark 1,062.$					
accordance with BMW specifications. (2x).  To check electrical wiring system					
To replace electromechanical power steering including program, initialize steering column adjustment and conduct check for proper function. $\xi \mu_{\text{o}} = 885.00$					
To suply tyre 225/40R18 Bridgestone $80\%$ TN $990\sqrt{362.5}$					
To replace front windscreen glass. 574.00,  To conduct water leak tests. 75.00,					
To remove and install IU unit bracket. 31.00					
To supply and install front or rear windscreen solar film.					
Towing : #150 / Sundries \$150 /	Total Labour 1: 6,446.50				
DESCRIPTION	BT 1 286.15 286.15 \\ BT 1 192.00 192.00 \\ NEC 4 8.05 32.20 \\ 1 511.30 511.30 \\ 1 506.35 506.35 \\ 1 364.70 364.70 \\ 1 5,244.75 5,244.75				