

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Tuesday, 30 August 2022 10:49 AM
To: Shiau Chan (LKKAUTO)
Subject: Re: AIS-OD SMZ 3605U SURVEYED BY STEVE (OUR REF: CS/AIS22004375/Eqy3)

Dear Shiau Chan,

Audit check done for SMZ3605U without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 30 August 2022 10:34 am
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: RE: AIS-OD SMZ 3605U SURVEYED BY STEVE (OUR REF: CS/AIS22004375/Eqy3)

Dear Simon,

For your re-audit. (Reduction)

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Sent: Thursday, 12 May 2022 9:17 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: AIS-OD SMZ 3605U SURVEYED BY STEVE (OUR REF: CS/AIS22004375/Eqy3)

Dear Shiau Chan,

Audit check done for SMZ3605U, found front windscreen cracked was not mention in GIA report.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiao Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Wednesday, 11 May 2022 3:43 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: AIS-OD SMZ 3605U SURVEYED BY STEVE (OUR REF: CS/AIS22004375/Eqy3)

Dear Simon,

For your audit.

Best Regards,

Shiao Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)