Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd To: ERGO Insurance Pte. Ltd.

8 Temasek Boulevard 51 Ubi Ave 1 #01-25 #04-01 Suntec Tower Three Paya Ubi Industrial Park Singapore 038988 Singapore 408933

12 Sep 2022 Attn: Ivy Yong Date:

Preliminary Advice

Insured Vehicle No : GBD9395G

TP Vehicle No : SHA3941P : 09/05/2022 Accident Date Make : HONDA ACCORD Assignment Date : 10/05/2022

Date of Inspection : 11/05/2022 Est. Duration of Repair : 15

Inspection At : BIFROST AUTO PTE LTD (SIN MING) (HQ)

BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE

SINGAPORE 575644

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	66,259.30
Revised Amount	:S\$	45,924.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	45,924.20
Lump Sum Repair	·S\$	33 600 00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to consistency check, part prices and labour cost.