

CS/EGI22004377/D<sup>3</sup>

ASSIGNMENT

CJB 2028 March

March 2020

Unit

Class

Estimated Cost

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s

Insured:

Policy No.

Claims No.

Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value:

JAC: Accident Report

Consistent? : Yes or No

SA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

15

days

Res.: Yes or No

Sum Sum:

20

%

3 Val.: Yes or No

SA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Vehicle SHIA 3941P

or Regd.

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

C.C. 1580

Colour

Blue

A/C

Insured / Std / NI / NA

Sp Reading

129649

T/Radio: Insured / Std / NI / NA

Eng/No.

G4LEKU407486

C/No:

KMHCB51CVLU189569

Gen. Cond: ~~Good~~ / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi: Nil / ~~SRim~~ / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

D.O.I.

11/05/2022

Survey held at

Bijest Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear y Rn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Bigo GBD 9395G

02/09/22

Sum 215 33,600/- with 15 days 7% (Red, 32659.30, 49%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 12/9/22

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

15

Resurvey No. of Trip:

2

Survey Fee:

Transportation

And Fee:

☐

Site Insp. US

☐

Interview US

☐

Photo US

☐

Video US

33600

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	821R
<b>Vehicle Details</b>	
Vehicle No.:	SHA3941P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 May 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU407486
Chassis No.:	KMHC851CVLU189569
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$26,033.00
Original Registration Date:	11 Mar 2020
First Registration Date:	11 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$13,447.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Mar 2028
PARF Rebate Amount:	\$10,085.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$26,566.00
COE Rebate Amount:	\$19,371.00
<b>Total Rebate Amount:</b>	<b>\$29,456.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 May 2022

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	10/05/2022 18:22 (SGT)
Date of Accident	09/05/2022 20:00 (SGT)
Exact Location of Accident	Keppel Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3941P
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-91371414
Alternative Phone No	(Office) +65-65508768

#### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	AE IONIQ HEV FL 1.6 DCT
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

#### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

#### DRIVER

Name of Driver	ANG HONG YEW(HONG FENGYOU)
NRIC No	SXXXX383C



Date of Birth	20/09/1974
Occupation	Outdoor
Date Of Driving Pass	10/04/1995
Driving experience	27 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-91371414
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 466A SEMBAWANG DRIVE #15-315
Address complement	-
Postcode	751466
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	LUQMAN
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Sembawang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005549999
Police Station Address	4 Sembawang Crescent Singapore 757633
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

Refer to the Police Report

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9395G
Vehicle Manufacturer	-



Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	MUKUNDHU VIKRAM
Passport No/FIN	GXXXX892U
Contact Number	(Phone) +65-90223873
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLF6011E
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	DAVID
Contact Number	(Phone) +65-92319910
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LUQMAN
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	CHEST PAIN
Injured person in which vehicle?	SHA3941P
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

INJURED 2

Name of injured person	ANG HONG YEW(HONG FENGYOU)
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	Back pain
Injured person in which vehicle?	SHA3941P
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date & Time


Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

*[Signature]*

10/5/22 @ 1100H

*[Signature]*  
Witnessed by Reporting Centre Personnel *[Signature]*



A - SHA 3941P

B - GBD 9395G

C - SLF 6011E

KEppel RB

Describe Circumstances of the Accident

PLEASE REFER TO POLICE REPORT T /20220510/2002



Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

10/5/22 @ 1100H



# SINGAPORE POLICE FORCE

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999



T/20220510/2002

1 of 4

Report No. T/20220510/2002

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:  
10/05/2022 00:40

Vide Report No.:

Station Diary No.:  
12

### Informant's Particulars

Name of Informant:  
ANG HONG YEW

Address:  
APT BLK 466A SEMBAWANG DRIVE #15-315 SINGAPORE  
751466

ID Type / ID No.:  
NRIC NO / S7431383C

Contact No.:  
Home/Office:

Mobile: 91371414

Nationality:  
SINGAPORE CITIZEN

Email:

Sex: Male  
Age: 47  
Date of Birth: 20/09/1974

Type of Informant:  
Driver

Race:  
Chinese

Language:

Occupation:  
Taxi driver

Driving Licence Information:  
Class: 2B,2A,2,3,4

Date of Expiry:

### General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/05/2022 20:00	Type of Location:
Location: KEPPEL ROAD				
Weather:		Road Surface:		
Traffic Flow:		Road Speed Limit:		Traffic Control:
Type of Collision:		Traffic Volume:		Anyone conveyed by ambulance: No

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD9395G	Lorry				Slightly Damaged	1
SHA3941P	Car				Seriously Damaged	1
SLF6011E	Car				Slightly Damaged	1



**SINGAPORE  
POLICE FORCE**



T/20220510/2002

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

3 of 4

Report No. T/20220510/2002

**CONTINUATION OF REPORT**

Subsequently, we came down from our vehicles to make a check. My taxi was badly damaged and it was being towed on the spot. My front registration plate was broken and the rear vehicle was heavily dented in. The front vehicle was slightly damage at the rear. However, he had to drive off as he had a passenger. The behind lorry damages were the front bumper.

Ambulance and Traffic Police came down to the location. I was advised to lodge a report. My passenger was conveyed to SGH.

I have an in-car camera.



**SINGAPORE  
POLICE FORCE**



T/20220510/2002

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

4 of 4

Report No. T/20220510/2002

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

L /

SGT 3 WAN FARAH DINA BINTE  
SAIFULLIZAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

10/05/2022 00:40

Officer In Charge Of Case:

TP / GIT /

SR STAFF SGT ABDUL RAHIM BIN SALIM

Contact No.: 65476433

Classification Of Case:

NP168

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 10-May-22  
 MODEL: HYUNDAI IONIC  
 VEHICLE NO.: SHA 3941P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

INSURANCE:

Acknowledged by Repairer

Signature:

Date:

Description	Qty	List Price	Amount
Bonnet <i>Double</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH) <i>HH</i>	2	\$ 118.70	\$ 237.40
Bonnet Lock <i>st</i>	1	\$ 127.30	\$ 127.30
Bonnet Insulator <i>sv</i>	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips <i>HH</i>	1	\$ 15.00	\$ 15.00
Flap Assy Active Air Upper, (LH/RH) <i>broken / mostly broken</i>	2	\$ 824.60	\$ 1,649.20
Flap Assy Active wire <i>wire torn</i>	1	\$ 765.30	\$ 765.30
Front Number Plate garnish <i>adjusted</i>	1	\$ 188.00	\$ 188.00
Front Bumper Cover <i>Double / torn</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>torn / crack</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>torn</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>st</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH/RH) <i>st / Double</i>	2	\$ 186.50	\$ 373.00
Front Bumper Towing Cover <i>HH</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>broken</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>HF</i>	1	\$ 93.60	\$ 93.60
Front Bumper Bracket Top (LH/RH) <i>broken</i>	2	\$ 85.00	\$ 170.00
Front Bumper Bracket (LH/RH) <i>sv</i>	2	\$ 75.00	\$ 150.00
Front Bumper Retainer Mounting (LH/RH) <i>HH</i>	2	\$ 95.00	\$ 190.00
Front Bumper Clips 10 pcs <i>HH</i>	1	\$ 45.00	\$ 45.00
Front Bumper Grille (LH/RH) <i>HH</i>	1	\$ 186.90	\$ 186.90
Headlamp Support Panel Assy <i>broken</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH/RH) <i>crack / broken 2110-30x2</i>	2	\$ 3,987.30	\$ 7,974.60
Horn Unit (LH/RH) <i>HS Dam o/s HH</i>	2	\$ 72.80	\$ 145.60
Horn Wire <i>HH</i>	1	\$ 386.70	\$ 386.70
Radiator Inverter <i>st / punctured</i>	1	\$ 884.80	\$ 884.80
Radiator <i>st / punctured</i>	1	\$ 710.50	\$ 710.50
Radiator fan blower motor assy <i>broken</i>	1	\$ 1,459.60	\$ 1,459.60
Radiator Air Guard (LH/RH) <i>o/s HH HS torn</i>	2	\$ 76.40	\$ 152.80
Radiator Air Guard, Upr (LH/RH) <i>HH</i>	2	\$ 127.50	\$ 255.00
Front Fender(LH) <i>sv / Double</i>	1	\$ 490.70	\$ 490.70
Front Fender Shield (LH) <i>HH</i>	1	\$ 164.70	\$ 164.70
Air Duct <i>HH</i>	1	\$ 156.80	\$ 156.80
air duct hose <i>HH</i>	1	\$ 86.40	\$ 86.40
Aircon Condenser <i>st / punctured</i>	1	\$ 663.60	\$ 663.60
Frt Door(LH/RH) <i>HH / sv</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>HH</i>	1	\$ 250.00	\$ 250.00
Frt Safety Belt(Assy)(LH/RH) <i>adjusted</i>	2	\$ 648.90	\$ 1,297.80
Rear Safety Belt(Assy)(LH/RH) <i>adjusted</i>	2	\$ 513.20	\$ 1,026.40
Rear Safety Belt Garnish Cover(LH/RH) <i>crack / mostly</i>	2	\$ 398.00	\$ 796.00
Front Windscreen Glass <i>crack / broken</i>	1	\$ 1,558.10	\$ 1,558.10
Front Windscreen Moulding <i>HH</i>	1	\$ 157.30	\$ 157.30

4220.60

22,775.00

Dashboard Complete <i>broken</i>	1	\$ 4,724.00	\$ 4,724.00
Passenger Air Bag <i>actived</i>	1	\$ 2,633.00	\$ 2,633.00
Steering Airbag Complete <i>actived</i>	1	\$ 1,090.90	\$ 1,090.90
Airbag Control Module <i>actived</i>	1	\$ 1,243.70	\$ 1,243.70
Knee control airbag module assy <i>actived</i>	1	\$ 578.60	\$ 578.60
Steering Angle Assy <i>HN</i>	1	\$ 786.90	\$ 786.90
Sensor Assy Impact -Frt Impact <i>HN</i>	1	\$ 643.90	\$ 643.90
Airbag Sensor (LH/RH) <i>actived</i>	2	\$ 348.10	\$ 696.20
Boot Lid <i>Double</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>turn / doimed</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>1/2</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>HN</i>	2	\$ 86.70	\$ 173.40
Boot Lid Lock Upper <i>1/2 / 2mm</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>HN</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>HN</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>HN</i>	1	\$ 31.30	\$ 31.30
Boot Lid Lamp(LH/RH) <i>crack / cut</i>	2	\$ 822.00	\$ 1,644.00
Boot Lid Trimboard <i>HN</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>HN</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>HN</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>HN</i>	2	\$ 92.50	\$ 185.00
Boot Lid Trimboard REAR <i>HN</i>	1	\$ 124.80	\$ 124.80
Boot Lid Glass, Upper <i>HN</i>	1	\$ 907.20	\$ 907.20
Boot Lid Glass, Lower <i>broken</i>	1	\$ 584.90	\$ 584.90
Boot Lid Glass Upper Moulding <i>HN</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HN</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>turn / Double</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>crack / broken</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>broken / Double</i>	2	\$ 188.10	\$ 376.20
Antenna Assy-SMARTK outer <i>monny broken</i>	1	\$ 689.50	\$ 689.50
Rear Bumper Centre Moulding Assy <i>turn / Double</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>monny broken</i>	1	\$ 47.50	\$ 47.50
Rear Bumper Stay <i>HN</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH/RH) <i>SN</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>HN</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>monny broken</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>O/S HN N/S broken</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Rear Hook <i>HN</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(LH/RH) <i>O/S HN N/S cut</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Towing Cover <i>HN</i> <i>socket</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>socket</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>HN</i> <i>broken</i>	1	\$ 193.53	\$ 193.53
Licence Lamp WIRE <i>HN</i>	1	\$ 135.80	\$ 135.80
Tail Lamp(LH/RH) <i>cut</i>	2	\$ 870.40	\$ 1,740.80
Tail Lamp Quarter Panel(LH/RH) <i>O/S HN N/S Double</i>	2	\$ 208.90	\$ 417.80
Rear Panel <i>Double</i> <i>rep</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>doimed</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>broken</i>	1	\$ 223.10	\$ 223.10
Spare Wheel Lock Nut <i>1/2</i>	1	\$ 89.50	\$ 89.50
Spare Tyre Panel <i>Double</i>	1	\$ 892.50	\$ 892.50
Panel Assy-Rear Floor Side (LH/RH) <i>O/S HN N/S Double</i>	2	\$ 39.40	\$ 78.80
Rear tray tools box RH <i>HN</i>	1	\$ 675.30	\$ 675.30
Rear tray tools box LH <i>broken</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>doimed</i>	1	\$ 354.20	\$ 354.20

24.62% - 70

Exhaust Pipe Insulator <i>HH</i>	1	\$ 235.00	\$ 235.00
Exhaust Silencer <i>HH</i>	1	\$ 943.50	\$ 943.50
Exhaust Pipe Hanger <i>HH</i>	1	\$ 29.20	\$ 29.20
SUB TOTAL			\$ 62,261.83
LESS 20%			\$ 12,452.37
DISCOUNTED TOTAL			\$ 49,809.46
Front Number Plate <i>dislodged</i>	SN 1	\$ 25.00	\$ 25.00
Front No Plate Trim Cover <i>dislodged</i>	SN 1	\$ 30.00	\$ 30.00
COOLANT <i>HH</i>	SN 1	\$ 45.00	\$ 45.00
Emblem-Blue Drive (LH) <i>see Hec</i>	SN 1	\$ 26.60	\$ 26.60
Front Door Comfort Logo (LH/RH) <i>HH Hec</i>	SN 1	\$ 75.00	\$ 75.00
Front Windscreen Sealant <i>Hec</i>	SN 1	\$ 46.00	\$ 46.00
Front ERP BRACKET <i>Hec</i>	SN 1	\$ 30.00	\$ 30.00
INVERTER COOLANT <i>HH</i>	SN 1	\$ 65.00	\$ 65.00
Boot Lid Comfort Logo & Tel No. Sticker <i>Hec</i>	SN 1	\$ 35.00	\$ 35.00
Boot Lid Comfort Cablink Tel No. Sticker <i>HF</i>	SN 1	\$ 30.00	\$ 30.00
Rear No. Plate + Trim Cover <i>white / broken</i>	SN 1	\$ 45.00	\$ 45.00
Rear Windscreen Sealant <i>Hec</i>	SN 2	\$ 46.00	\$ 92.00
Rear Bumper Rubber Mat <i>damaged</i>	SN 1	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor <i>Down</i>	SN 1	\$ 180.00	\$ 180.00
SPARE TYRE PANEL TOP COVER SILICON <i>Hec</i>	SN 1	\$ 250.00	\$ 250.00
SUB TOTAL			\$ 1,024.60
<b>Labour Charge</b>			
Panel Beating	1	\$2,000.00	\$2,000.00
Spray Painting Charge	1	\$2,000.00	\$2,000.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00
Re-set Frt Power Window System	1	\$200.00	\$200.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Remove/Refix Front Windscreen Glass	1	\$120.00	\$120.00
Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat	1	\$550.00	\$550.00
Reset Safety Belt	1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$6,710.00
ESTIMATE TOTAL			\$ 57,544.06
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance			

47,403.70

37,922.96

451-

✓ List

✓

✓

✓

✓

✓

✓

✓

✓

✓

501-

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

✓

648.00

1400/-

1200/-

30/-

40/-

HH

80/-

120/-

40/-

HH

HH

HH

50/-

80/-

80/-

180/-

150/-

✓

✓

✓

✓

✓

✓

✓

✓

42,020.96

4533,600/-

Photo after repair with damaged parts.

2KE and

Provide BV before judgment.

66259.3

# BIFROST AUTO PTE LTD

## SUPPLEMENTARY REPAIR ESTIMATE

DATE: 17-May-22

INSURANCE: ERGO

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 3941 P

Description	Qty	List Price	Amount
Aircon metal hose - big Small Detail	1	\$ 352.10	\$ 352.10
Speaker CRBKE	1	\$ 256.10	\$ 256.10
Electronic clutch pump CRBKE	1	\$ 4,386.50	\$ 4,386.50
Rear Spoiler CRBKE	1	\$ 665.40	\$ 665.40
Spare Tyre Panel sign	1	\$ 892.50	\$ 892.50
Rear Fender(LH) Detail	1	\$ 1,768.30	\$ 1,768.30
Rear Fender Trim Board (LH) Bt	1	\$788.75	\$ 788.75
Assy BSD Blind Spot Radar (LH) mandy Bt	1	\$1,784.40	\$ 1,784.40
SUB TOTAL			\$ 10,894.05
LESS 20%			\$ 2,178.81
DISCOUNTED TOTAL			\$ 8,715.24
ESTIMATE TOTAL			\$ 8,715.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: [claims\\_ltr@bifrostable.com](mailto:claims_ltr@bifrostable.com)

  
Lkk And



S/N.	PARTS		NETT	S/NETT	LABOUR
1	\$ 2,253.80	\$ 142.60	\$ 1,784.40		
2	\$ 127.30	\$ 224.00			
3	\$ 1,649.20	\$ 28.00			
4	\$ 765.30	\$ 24.30			
5	\$ 188.00	\$ 31.30			
6	\$ 481.10	\$ 1,644.00			
7	\$ 476.30	\$ 584.90			
8	\$ 186.90	\$ 459.40			
9	\$ 1,136.70	\$ 394.80			
10	\$ 373.00	\$ 376.20			
11	\$ 368.50	\$ 689.50			
12	\$ 170.00	\$ 451.25			
13	\$ 45.00	\$ 47.50			
14	\$ 1,139.30	\$ 22.00			
15	\$ 4,220.60	\$ 123.85			
16	\$ 72.80	\$ 123.10			
17	\$ 884.80	\$ 82.90			
18	\$ 710.50	\$ 328.60			
19	\$ 1,459.60	\$ 1,740.80			
20	\$ 76.40	\$ 208.90			
21	\$ 490.70	\$ 532.00			
22	\$ 663.60	\$ 346.80			
23	\$ 1,297.80	\$ 223.10			
24	\$ 1,026.40	\$ 89.50			
25	\$ 796.00	\$ 892.50			
26	\$ 1,558.10	\$ 39.40			
27	\$ 157.30	\$ 693.20			
28	\$ 4,724.00	\$ 354.20			
29	\$ 2,633.00	\$ 26.60			
30	\$ 1,090.90	\$ 352.10			
31	\$ 1,243.70	\$ 256.10			
32	\$ 578.60	\$ 4,386.50			
33	\$ 696.20	\$ 665.40			
34	\$ 2,549.70	\$ 1,768.30			
35	\$ 187.40	\$ 788.75			
36					
	\$ 36,478.50	\$ 19,142.35	\$ 1,784.40	\$ -	\$ -
		Sub Total:	\$ 57,405.25	10%	
		20%	\$ 11,481.05	-	
			\$ 45,924.20	-	
				TOTAL:	\$ 45,924.20
				80% Lump Sum:	\$ 36,739.36
				Round Off:	\$ 33,600.00