



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004378/Uqy3s2	
			Date: 30/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 960K	Veh. Inspected	SKJ 9287Y	
Policy No.	D20MTPV01010310	Coverage (\$)	0.00	
Claim No.	CMTD2201593/AGC	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	10/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA RAV-4 (A)	c.c	1987	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTMDE3EV90D014593	Colour	WHITE	
Odometer	72879 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	DUNLOP	6 mm	
L/H Front Tyre	225/65 R17	DUNLOP	6 mm	
R/H Rear Tyre	225/65 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/65 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/05/2022	Inspection Date	10/05/2022	
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	