



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004379/Uqy3n2	
			Date: 30/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKQ 6518P	Veh. Inspected	SMN 476H
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201536/LOR	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	10/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	NHP1707168568	Colour	RED
	Odometer	202637 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	INTERTRAC	6 mm
	L/H Front Tyre	185/60 R15	INTERTRAC	6 mm
	R/H Rear Tyre	185/60 R15	INTERTRAC	6 mm
	L/H Rear Tyre	185/60 R15	INTERTRAC	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/05/2022	Inspection Date	12/05/2022
	Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	