

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	NCE LTD		Ref:	CS/INC22004382/Bqy3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	27/02/2023	
	ATTN: CYNDIIE YO	ONG		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SML 1718P	Veh. Inspected		SME 3941J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1171636-001	Excess (\$)		0.00	
	Assign From	JESS TOH	Assign Date		10/05/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA CX-5	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6KF2W7AK0232718	Colour		BLACK	
	Odometer	76447 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/65 R17	FALKEN		5 mm	
	L/H Front Tyre	225/65 R17	FALKEN		5 mm	
	R/H Rear Tyre	225/65 R17	FALKEN		5 mm	
	L/H Rear Tyre	225/65 R17	FALKEN		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	08/05/2022	Inspect Date /	Time	11/05/2022 (02:00 PM)	
	Survey held at	BIFROST AUTO PTE LTD				
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				