

BIFROST AUTO PTE LTD
 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Repair Estimate

Vehicle number: SME3941J
 Make & Model: Mazda CX-5
 Chassis number: JM6KF2W7AK0232718

Date of survey: _____
 Name of surveyor: _____
 Contacts: _____

No.	Description of spare parts	Qty	Amount S\$	
1	Bonnet	1	\$ 1,015.00	DD ✓
2	Bonnet insulator	1	\$ 237.00	NNX
3	Bonnet insulator clips	1set	\$ -50.00	NDX
4	Bonnet RH hinge	1	\$ -78.00	NDX
5	Bonnet LH hinge	1	\$ -78.00	NNX
6	Bonnet lock	1	\$ 176.00	DD ✓
7	Bonnet weatherstrip	1	\$ -76.00	NECV
8	Front bumper	1	\$ 1,033.00	MSX
9	Front bumper clips	1set	\$ 30.00 60.00	NDX
10	Front bumper RH fog lamp cover	1	\$ 129.00	SC ✓
11	Front bumper RH fog lamp	1	\$ 453.00	NECV
12	Front bumper inner lower garnish	1	\$ -145.00	NDX
13	Front bumper number plate garnish	1	\$ 109.00	SC ✓
14	Front bumper RH distance sensor	1	\$ 233.00	NECV
15	Front bumper LH distance sensor	1	\$ 233.00	NDX
16	Front bumper distance sensor holders	2	\$ 60 92.00	NDX
17	Front bumper distance sensor wire harness	1	\$ -89.00	NECV
18	Front bumper reinforcement	1	\$ -617.00	NDX
19	Front bumper reinforcement air guard	1	\$ -145.00	NECV
20	Front bumper RH side retainer	1	\$ 22.00	BR ✓
21	Front bumper LH side retainer	1	\$ 22.00	BR ✓
22	Front bumper sponge RH	1	\$ 55.00	NECV
23	Front grille	1	\$ 1,087.00	BR ✓
24	Front grille emblem	1	\$ 98.00	NECV
25	Front grille emblem base	1	\$ 89.00	BR ✓
26	Front grille RH chrome moulding	1	\$ 178.00	NDX
27	Front grille LH chrome moulding	1	\$ -178.00	NECV
28	Front grille RH inner bracket	1	\$ 78.00	NNX
29	Front grille LH inner bracket	1	\$ 78.00	NDX
30	Front grille rivets	6	\$ -35.00	NDX
31	Front grille top garnish	1	\$ 145.00	BR ✓
32	RH headlamp assy	1	\$ 3,568.00	NNX
33	LH headlamp assy	1	\$ 3,568.00	DD ✓
34	Front RH fender	1	\$ 415.00	DIS ✓
35	Front RH fender arch moulding	1	\$ 198.00	NECV
36	Front RH fender arch moulding clips	1set	\$ 30.00 60.00	NDX
37	Front RH fender splash shield	1	\$ 98.00	BR ✓
38	Front RH fender splash shield clips	1set	\$ 50.00	NNX
39	Front upper panel	1	\$ -156.00	DD ✓
40	Front stay lock	1	\$ -45.00	NNX

NDX
BRV
NDX

10216

ADX

NNX

Total:	\$	3,700.00
--------	----	----------

Spare Parts:	\$	16,534.40
Special Nett:	\$	670.00
Labour:	\$	3,700.00
Total Amount:	\$	21,004.40

Survey & Resurvey

11/5/2022

TGlin Mn

1500hrs

Lump sum repair

Repair days 8

9552.80
x 80%
7642.24

L/S 7600

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: