

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Repair Estimate**

Vehicle number: SND6700L

Make &amp; Model: BMW X3

Chassis number: WBAWY920800Y20926

Date of survey: \_\_\_\_\_

Name of surveyor: \_\_\_\_\_

Contacts: \_\_\_\_\_

| No. | Description of spare parts                | Qty  | Amount S\$                |
|-----|---|------|---------------------------|
| 1   | Rear bumper                               | 1    | \$ <del>1,409.30</del>    |
| 2   | Rear bumper reverse sensor rubber seal    | 4    | \$ 21.20                  |
| 3   | Rear bumper reverse sensor holders        | 4    | \$ 128.40                 |
| 4   | Rear bumper clips                         | 1set | \$ 60.00                  |
| 5   | Rear bumper RH side retainer              | 1    | \$ 141.83                 |
| 6   | Rear bumper LH side retainer              | 1    | \$ 141.83                 |
| 7   | LH rear fender                            | 1    | \$ <del>1,643.70</del>    |
| 8   | LH rear fender glass with rubber moulding | 1    | \$ 715.80                 |
| 9   | LH rear fender arch moulding              | 1    | \$ <del>258.90</del>      |
| 10  | LH rear fender arch moulding clips        | 1set | \$ 60.00                  |
| 11  | LH rear sport rim (original)              | 1    | \$ <del>1,151.37</del>    |
| 12  | LH rear wheel bearing                     | 1    | \$ <del>155.80</del>      |
| 13  | LH rear knuckle arm                       | 1    | \$ <del>1,106.80</del>    |
| 14  | LH rear shock absorber                    | 1    | \$ <del>340.50</del>      |
| 15  | LH rear lower arm                         | 1    | \$ <del>347.55</del>      |
| 16  | LH rear upper arm                         | 1    | \$ 578.30                 |
| 17  | LH rear door 1387                         | 1    | \$ 1,478.50               |
| 18  | LH rear door weatherstrip ✓               | 1    | \$ 135.70                 |
| 19  | LH rear door inner trim board             | 1    | \$ 782.44                 |
| 20  | LH rear door inner trim board clips       | 1    | \$ 60.00                  |
| 21  | LH front door 1387                        | 1    | \$ 1,550.23               |
| 22  | LH front door weatherstrip ✓              | 1    | \$ 155.60                 |
| 23  | LH front door emblem 67                   | 1    | \$ 78.00                  |
| 24  | LH front door inner trim board clips      | 1    | \$ 60.00                  |
| 25  | LH front door inner trim board            | 1    | \$ 782.44                 |
| 26  | LH side rocker panel spoiler 408          | 1    | \$ 878.43                 |
| 27  | LH side rocker panel spoiler clips ✓      | 1set | \$ <del>30.00</del> 60.00 |
|     |   |      |                           |
|     |   |      |                           |
|     |   |      |                           |
|     |   |      |                           |

Parts less 5% \$ 14,282.62 3569  
Total \$ 714.13 178  
\$ 13,568.49 3391

| No. | Special Nett Items | Amount S\$ |
|-----|--------------------|------------|
|-----|--------------------|------------|

|        |                                 |   |           |
|--------|---------------------------------|---|-----------|
| 1      | LH rear fender glass sealant    | 1 | \$ 70.00  |
| 2      | LH rear fender glass inner seal | 1 | \$ 50.00  |
| 3      | LH rear tyre                    | 1 | \$ 650.00 |
| 4      | Brake fluid                     | 1 | \$ 80.00  |
|        |                                 |   |           |
|        |                                 |   |           |
| Total: |                                 |   | \$ 850.00 |

NNX

| No.    | Labour and painting  | Amount S\$                    |
|--------|--|-------------------------------|
| 1      | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas | <del>\$ 600.00</del> 2,000.00 |
| 2      | Spray painting on affected areas and panels  | <del>\$ 600.00</del> 1,600.00 |
| 3      | Check wiring and lighting system on affected areas   | \$ 100.00                     |
| 4      | Apply rust coating chemical on affected areas and panels   | \$ 120.00                     |
| 5      | Remove and reinstall rear bumper reverse sensor, rubber seal and holders to assist repair  | \$ 100.00                     |
| 6      | Remove and reinstall rear bumper inner trims, garnish and boards to assist repair  | \$ 320.00                     |
| 7      | Remove and replace rear undercarriage parts  | \$ 550.00                     |
| 8      | Adjust and test drive wheel alignment system   | \$ 150.00                     |
| 9      | Remove and replace LH rear door inner mechanism to new door  | <del>\$ 80.00</del> 180.00    |
| 10     | Remove and replace LH front door inner mechanism to new door   | <del>\$ 80.00</del> 180.00    |
| 11     | Remove and reinstall roof lining, seats, seat belts and carpet to assist repair  | \$ 550.00                     |
| 12     | Reset control unit and diagnose fault code after repair  | \$ 350.00                     |
|        |  |                               |
|        |  |                               |
|        |  |                               |
| Total: |  | \$ 6,200.00                   |

NNX

NNX

1360

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Survey & Resurvey

11/5/2022 TGM Inc

1420 hrs

Lump sum repair

Repair days 7

Spare Parts: \$ 13,568.49

Special Nett: \$ 850.00

Labour: \$ 6,200.00

Total Amount: \$ 20,618.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: