



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22004384/Bvy3e2

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 26/05/2023

ATTN: AZHARI

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLG 2663U	<b>Veh. Inspected</b>	SKV 5128L
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1153949-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JESS TOH	<b>Assign Date</b>	10/05/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 3	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	JM6BM42A8G0318270	<b>Colour</b>	BLUE
<b>Odometer</b>	87898 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	MICHELIN	6 mm
<b>L/H Front Tyre</b>	205/60 R16	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	08/12/2021	<b>Inspect Date / Time</b>	11/05/2022 ( 01:21 PM )
<b>Survey held at</b>	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**