

ESTIMATED REPAIR COST DETAILS

ACC22050004

To: NTUC INCOME INSURANCE CO-OPERATIVE LTD
1 MARITIME SQUARE
#10-01 HARBOUR FRONT CENTRE
SINGAPORE 099253

Date: 12/05/2022
Vehicle No.: SKZ-9542-B
Make: MITSUBISHI
Model: ATTRANGE
Chassis No.: A13ASTHHR
YoM:

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	REAR BOOT LID <i>bt</i>	\$865.00	6257 20% 5005.60
1	REAR BOOT LID LOGO <i>ae</i>	\$78.00	
1	REAR BOOT LID EMBLEM - ATTRANGE <i>ae</i>	\$75.00	
1	REAR BOOT LID INSULATOR <i>X</i> nn	-	
1	REAR BOOT LID TOP CHROME <i>? cm</i>	\$265.00	
1	REAR BOOT LID EMBLEM - MIVEC <i>ae</i>	\$75.00	
1	REAR BOOT LID EMBLEM - CC <i>ae</i>	\$75.00	
1	REAR BOOT LID LOCK <i>? cm</i>	\$285.00	
1	REAR BOOT LID LOCK ACTUATOR <i>X</i> nn	\$375.00	
1	REAR BOOT LID WEATHERSTRIP <i>cut</i>	\$189.00	
1	REAR BUMPER <i>de</i>	\$859.00	
1	REAR BUMPER RETAINER LH <i>X</i> nn	\$88.00	
1	REAR BUMPER RETAINER RH <i>? cm</i>	\$88.00	
1	REAR BUMPER REFLECTOR LH <i>X</i> nn	\$97.00	
1	REAR BUMPER REFLECTOR RH <i>X</i> nn	\$97.00	
1	REAR BUMPER REINFORCEMENT <i>X</i> nn	\$368.00	
1	REAR END PANEL <i>bt</i>	\$512.00	
1	REAR END PANEL TOP GARNISH <i>? de</i>	\$215.00	
1	SPARE TYRE BOARD <i>cm</i>	\$368.00	
1	SPARE TYRE COMPARTMENT <i>X</i> nn	\$1,180.00	
1	TAIL LAMP RH <i>cm</i>	\$589.00	
1	TAIL LAMP PANEL RH <i>X</i> nn	\$265.00	
1	TAIL LAMP LH <i>? cm</i>	\$589.00	
1	REAR FENDER (RH) <i>bu</i>	\$915.00	
1	REAR FENDER INNER TRIM RH <i>X</i> nn	\$482.00	
1	REAR SMART KEYLESS ANTENA <i>? cm</i>	\$215.00	
1	REAR FENDER SHIELD RH <i>X</i> nn	\$78.00	
Sub Total		\$9,287.00	

ESTIMATED REPAIR COST DETAILS

ACC22050004

Discount 20% on Parts

(~~\$1,857.40~~)

\$7,429.60

Special Nett

10	REAR BUMPER CLIPS <i>nn</i>	
1	REAR REVERSE SENSR SET <i>nn</i>	
1	REAR NUMBER PLATE WITH FRAME <i>nn</i>	
Sub Total		

\$50.00	30	} 230
\$280.00	200?	
\$50.00	X	
\$380.00		

Labour & Misc

TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS
TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR
PARTS, INCLUSIVE OF REPLACEMENT PARTS
LABOUR TO SPRAY PAINT REAR AFFECTED AREAS
DISCONNECT AND CHECK ELCTRICAL WIRING, HARNESS,
WIRE SOCKET
TO SUPPLY UBDER COATING/PUTTY ON PARTS REPLACED
TO PERFORM WATER SEEPAGE TEST AFTER REPAIR
REMOVE AND REPLACE REVERSE SENSOR
TO REALIGN REAR EXHAUST SYSTEM
DISMANTLE AND TRANSFER TAILGATE FITTINGS AND
MECHANISM TO NEW BOOT LID/FACILITATE REPAIR
REMOVE AND REFIT END PANEL LINING AND GARNISH TO
FACILITATE REPAIR
Sub Total

\$1,000.00	800	} 1880
\$1,200.00	800	
\$80.00	30	
\$60.00	40	
\$60.00	30	
\$80.00	60	
\$80.00	X	
\$150.00	60	
\$80.00	60	
\$2,790.00		

Sub Total

\$10,599.60

GST 0%

Total

\$10,599.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5005.60

230.00

1880.00

7115.60

20%

5692.48

48- \$5,700

Resur
Hp 90010068
8 days
4/5
11/05/22 @ 1455
Resur after repair