

FC AUTO GARAGE PTE LTD
8 KAKI BUKIT AVE 4
#04-03 PREMIER@KB
SINGAPORE 415875
Mobile: 90110243
Co. Reg. No.: 202115045W



ESTIMATED REPAIR COST DETAILS

ACC22050002

To: NTUC INCOME INSURANCE CO-OPERATIVE LTD
1 MARITIME SQUARE
#10-01 HARBOUR FRONT CENTRE
SINGAPORE 099253

Date: 11/05/2022
Vehicle No.: SNB-6575-S
Make: MERCEDES BENZ
Model: GLB200 AMG LINE
PREMIUM
Chassis No.: W1N2476872W083555
YoM: 2020

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	FRONT DOOR (LH) <i>bt</i>	\$2,158.50	
1	FRONT DOOR HINGE UPPER (LH) <i>Xsu</i>	\$12.50	X
1	FRONT DOOR HINGE LOWER LH <i>bt Xsu</i>	\$136.80	X
1	FRONT DOOR INNER TRIM BOARD LH <i>Xsu</i>	\$930.40	X
1	FRONT DOOR WEATHERSTRIP LH <i>re</i>	\$405.00	
1	FRONT DOOR PROTECTOR (LH) <i>sc</i>	\$85.60	
1	FRONT DOOR PROTECTOR CHROME MOULDING LH <i>re</i>	\$215.60	
1	FRONT DOOR PROTECTOR LOWER STRIP LH <i>sc ? sc</i>	\$86.90	
1	REAR DOOR LH <i>bt</i>	\$2,875.00	
1	REAR DOOR HINGE UPPER LH <i>Xsu</i>	\$136.20	X
1	REAR DOOR HINGE LOWER LH <i>bt</i>	\$128.70	
1	REAR DOOR CHECKER LH <i>bt</i>	\$110.50	
1	REAR DOOR WEATHERSTRIPE L/H <i>re</i>	\$415.60	
1	REAR DOOR PROTECTOR LH <i>sc</i>	\$95.60	
1	REAR DOOR PROTECTOR CHROME MOULDING LH <i>re</i>	\$280.70	
1	REAR DOOR INNER TRIM BOARD LH <i>sc</i>	\$835.60	
1	REAR DOOR ARCH LH <i>sc</i>	\$275.00	
1	REAR BUMPER <i>repair</i>	\$1,245.20	X R
1	REAR BUMPER RETAINER LH <i>Xsu</i>	\$113.40	X
1	REAR FENDER LH <i>repair</i>	\$7,500.40	X R
1	REAR FENDER SHIELD LH <i>Xsu</i>	\$287.90	X
1	REAR KNUCKLE HUB LH <i>? bt</i>	\$1,540.60	
1	REAR ABSORBER (LH) <i>Xsu</i>	\$415.60	X
1	REAR WHEEL BEARING LH <i>? bt</i>	\$525.40	
1	REAR EXHAUST TRIM CHROME LH <i>sc Xsu</i>	\$185.40	X
1	FRONT DOOR LOCK LH <i>Xsu</i>	\$630.50	X
1	REAR DOOR LOCK LH <i>sc</i>	\$630.50	
1	REAR DOOR OUTER MOULDING CHROME LH <i>Xsu</i>	\$287.30	X

ESTIMATED REPAIR COST DETAILS

ACC22050002

1 REMOVE AND REFIT DOOR WINDOW GLASS TO *nn*
FACILITATE REPAIR

\$120.00 *X*

1 REAR LOWER ARM LH *X300*

\$125.60 *X*

1 REAR UPPER ARM LH *241*

\$258.40

1 CENTRE DOOR PILLAR L/H *X300*

\$1,897.40 *X*

Sub Total

\$24,947.80

Discount *5%* on Parts

(\$1,247.39)

\$23,700.41

10923.20
10%
9830.88

Rearu
Hp 90010068
7 days
4S

Special Nett

1 REAR TYRE - LH *cut 70%*

560 \$800.00

1 REAR SPORT RIM - LH *scu*

500 \$1,200.00 *? price*

10 REAR BUMPER CLIPS SET *Xnn*

\$90.00 *X*

10 REAR FENDER INNER SHIELD CLIPS LH *Xnn*

\$90.00 *X*

Sub Total

\$2,180.00

1060

11/05/22 @ 1510
Reg after repair

Labour & Misc

TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS
TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR
PARTS, INCLUSIVE OF REPLACEMENT PARTS

800 \$1,400.00

TO PUTTY AND RESPRAY PAINTING ON ALL ACCIDENT
DAMAGE PARTS AND OTHER ACCIDENT

800 \$1,800.00

DISCONNECT AND CHECK ELCTRICAL WIRING, HARNESS,
WIRE SOCKET

60 \$80.00

CHECK AND RE-ADJUST WHEEL ALIGNMENT

60 \$100.00

DISMANTLE AND TRANSFER FRONT/REAR DOOR FITTINGS
AND MECHANISM TO NEW BOOT LID/FACILITATE REPAIR

120 \$250.00

RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC
FAULT E.G. ABS, SRS, ECU MEMORY ETC

150 \$250.00

TO REALIGN REAR EXHAUST SYSTEM

Xnn \$100.00

TO PERFORM WATER SEEPAGE TEST AFTER REPAIR

30 \$80.00

TO CHECK, RESET & DIAGNOS ENGINE MANAGEMENT
WARNING LIGHT

Xnn \$80.00

Sub Total

\$4,140.00

9830.88

1060.00

Sub Total

2020.00

GST 0%

12910.88

Total

20%

10328.70

H/S - \$10,300 / 7 days

\$30,020.41

\$30,020.41

UKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: