

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Xiao Chen.

DATE : 09.05.22

TO : **ALLIED** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLK2271X**
MODEL : **HONDA HRV**
DATE OF ACCIDENT : 09.05.22
TIME OF ACCIDENT : 10:20HRS

JHMR418106X201793.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR FENDER INNER TRIM <i>3 NP</i>	2	\$ 250.70	\$ 501.40
2	REAR FENDER COWLING <i>3 NP</i>	2	\$ 133.40	\$ 266.80
3	REAR FENDER ARCED GARNISH <i>RH cracked</i>	2	\$ 195.40	\$ 390.80
4	REAR BUMPER <i>Delnd</i>	1	\$ 798.10	\$ 798.10
5	REAR BUMPER REFLECTOR <i>RH cracked</i>	2	\$ 156.30	\$ 312.60
6	REAR BUMPER SIDE <i>3 NP</i>	2	\$ 195.40	\$ 390.80
7	REAR BUMPER SIDE RETAINER <i>3 NP</i>	2	\$ 17.50	\$ 35.00
8	REAR BUMPER SENSOR C/W WIREHARNES <i>1 preamp</i>	4	\$ 350.80	\$ 1,403.20
9	TAILGATE <i>Dented</i>	1	\$ 1,100.90	\$ 1,100.90
10	TAILGATE EMBLEM 'HRV' <i>3 NP</i>	1	\$ 43.20	\$ 43.20
11	TAILGATE EMBLEM 'IVTEC' <i>3 NP</i>	1	\$ 28.70	\$ 28.70
12	TAILGATE INNER HOLDER <i>3 NP</i>	1	\$ 49.30	\$ 49.30
13	TAILGATE STOPPER <i>3 NP</i>	2	\$ 8.90	\$ 17.80
14	TAILGATE TOP LOCK <i>Damaged</i>	1	\$ 256.40	\$ 256.40
15	TAILGATE LOWER LOCK <i>3 NP</i>	1	\$ 34.50	\$ 34.50
16	TAILGATE LOCK ANTENA <i>3 NP</i>	1	\$ 80.20	\$ 80.20
17	TAILGATE INNER TRIM <i>3 NP</i>	1	\$ 153.40	\$ 153.40
18	TAILGATE WEATHER STRIP <i>Cut</i>	1	\$ 101.30	\$ 101.30
19	TAILGATE WINDSCREEN MOULDING (SET) <i>3 NP</i>	1	\$ 149.20	\$ 149.20
20	REVERSE CAMERA <i>3 NP</i>	1	\$ 629.40	\$ 629.40
21	BUZZER <i>3 NP</i>	1	\$ 80.20	\$ 80.20
22	REAR END PANEL <i>Dented</i>	1	\$ 411.90	\$ 411.90
23	REAR END PANEL TOP GARNISH <i>3 NP</i>	1	\$ 98.20	\$ 98.20
24	REAR FLOOR PANEL <i>3 NP</i>	1	\$ 787.50	\$ 787.50
25	REAR FLOOR PANEL BOTTOM GARNISH <i>3 NP</i>	1	\$ 190.20	\$ 190.20

TO : **ALLIED** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLK2271X**
 MODEL : **HONDA HRV**
 DATE OF ACCIDENT : 09.05.22
 TIME OF ACCIDENT : 10:20HRS

26	REAR FLOOR PANEL TOP BOARD <i>Not m</i>	1	\$ 260.40	\$ 260.40	<i>+</i>
----	---	---	-----------	-----------	----------

3037.60
 2430 08

TOTAL PRICE \$ 8,571.40
 LESS 20% \$ 1,714.28
SUB TOTAL PRICE \$ 6,857.12

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not m</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
2	REAR BUMPER CLIPS (SET) <i>Nec</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	TAIL LAMP CLIP (SET) <i>Not m</i>	1	\$ 40.00	\$ 40.00	<i>+</i>
4	TAILGATE OUTER GARNISH CLIP (SET) <i>Not m</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
5	TAILGATE INNER TRIM CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
6	TAILGATE WINDSCREEN SEALANT <i>3 m</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
7	TAILGATE WINDSCREEN INNER SEAL <i>Not m</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
8	REAR FENDER INNER TRIM CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
9	REAR FENDER COWLING CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
10	REAR FENDER ARCED GARNISH CLIP (SET) <i>Not m</i>	1	\$ 80.00	\$ 80.00	<i>20</i>
11	REAR END PANEL INSULATION SEAL <i>Not m</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>Not m</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
13	REAR FLOOR PANEL INSULATION SEAL <i>Not m</i>	1	\$ 280.00	\$ 280.00	<i>+</i>
14	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>Not m</i>	1	\$ 50.00	\$ 50.00	<i>+</i>

TOTAL \$ 1,240.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>+</i>

TO : **ALLIED** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLK2271X**
 MODEL : **HONDA HRV**
 DATE OF ACCIDENT : 09.05.22
 TIME OF ACCIDENT : 10:20HRS

8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2020

TOTAL \$ 4,890.00

TOTAL PARTS COST : \$ 8,097.12
 TOTAL LABOUR COST : \$ 4,890.00
 TOTAL REPAIR COST : \$ 12,987.12

Adrian Lj
L/s 11/05/22.
06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Total: 4630.08
L/s: 3.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: