

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/SMR21011644/Gty3-1	
STRIDES AUTOMOTIVE SERVICES PTE LTD				Ref: CS3/SMR21011644	
60 WOODLANDS INDUSTRIAL PARK				Date: 16/11/2021 10/05/2022	
E4SINGAPORE 757705				Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.	SHB 5175R		Veh. Inspected	FBM 4641G	
Policy No.			Coverage (\$)	0.00	
Claim No.	TAX/11/21/2011		Excess (\$)	0.00	
Assign From	HUA YEN JOEY		Assign Date	15/11/2021 10/05/2022	
2. Vehicle Particulars & Condition					
Make & Model			c.c	0	
Engine No.	HIDDEN		Year of Reg.		
Chassis No.			Colour		
Odometer	-		Steering		
Brakes			Modification		
General					
3. Conditions of Tyres					
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre			mm		
4. Description of Damages					
5. General Information					
Accident Date	08/11/2021		Inspection Date	16/11/2021	
Survey held at	KENG HOCK MOTOR 188 YIO CHU KANG ROAD, SINGAPORE 545635				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					