



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 4641G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|----------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | EXHAUST MUFFLER | BENT | 980.00 | 530.00 |
| 1 | EXHAUST MUFFLER PROTECTOR | SCRAPED / DENTED | 120.00 | 120.00 |
| 1 | RH BELLY PANEL | TO REPAIR SEE LABOUR | 185.00 | - |
| | LESS 10% DISCOUNT | | -128.50 | -65.00 |
| | | | 1,156.50 | 585.00 |
| | <u>LABOUR</u> | | | |
| | LABOUR FOR DISMANTLE AND REMOVE ALL DAMAGED PARTS, RENEW AND INSTALL NEW PARTS. INCLUSIVE OF THE REPAIR OF RH BELLY PANEL. | | 200.00 | 100.00 |
| | SPRAY PAINTING. | | 200.00 | 150.00 |
| | | | 400.00 | 250.00 |
| | GRAND TOTAL | | 1,556.50 | 835.00 |
| RECOMMENDED COST OF REPAIRS | | | | 835.00 |

Report Ref No. CS3/SMR21011644/Gty3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.