

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.
 \$25989.76
 10 Days. 7 Days.
 Veron

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 791 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00 ✓ ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 ✓ 250 + 250 500	lls
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	S/N \$ 1,700.00 ✓ 480	lls
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. BONNET AND BOTH HEADLIGHT. POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00 1000 + 1250 2250	lls
5	TO APPLY PROTECTION FILM ON HEADLIGHT AND PAINT COATING AT AFFECTED AREA. (BY OWNER)	S/N TBC ? 200	
6	TO RESPRAY FRONT BUMPER, BONNET AND HINGES. ✓	\$ 2,500.00 1100 ✓	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓ ✓	
TOTAL LABOUR CHARGES		\$ 10,472.00	

Originally 4 Days of repairs.
 Respray add 3 Days.
 therefore, 7 Days of
 repairs in total. #

Add 3 Days for the replacement
 of item (10) (Reinforcement Bracket)
 which requires the removal of
 lock carrier. lls. 10/06/22
 (Please inform HKK when the
 lock carrier is removed).

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 791 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
→ 1	FRONT BUMPER <i>Debond Repair</i>	1	TBC	✓ X	}
2	FRONT BUMPER RADIATOR GRILLE <i>Smashed</i>	1	TBC	✓ 2240	
3	FRONT BUMPER AIR GRILLE - LH / RH <i>RH crushed</i>	2	TBC	✓ X	
4	FRONT BUMPER FOAM <i>not new</i>	1	\$	139.00	X
5	FRONT BUMPER CARRIER <i>Dented</i>	1	\$	899.00	✓ 719.20
6	FRONT BUMPER TOP COVER <i>Debond</i>	1	\$	143.00	✓ 114
7	CAUTION STICKER <i>new</i>	1	\$	16.00	✓ 12.40
8	A/C STICKER	1	\$	9.00	✓ 6.64
9	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	82.00	X
10	FRONT BUMPER BRACKET (LH / RH) <i>Best</i>	2	\$	406.40 508.00	✓ ✓ <i>3 H.S.</i>
11	FRONT BUMPER CARRIER BRACKET <i>crushed</i>	1	\$	122.80 154.00	✓ ✓
12	FRONT BUMPER SUPPORT (LH / RH) <i>Anyd</i>	2	\$	51.04 64.00	✓ ✓
13	RIVET <i>new</i>	4	\$	4.00	✓ 2.88
14	FRONT BUMPER PARKING AID SENSOR - INNER / OUTER <i>not new</i>	4	\$	1,060.00	X
15	FRONT BUMPER PARKING AID SENSOR SEAL RING <i>new</i>	4	\$	10.00	? X
16	FRONT BUMPER WIRING SET <i>new</i>	1	\$	567.00	X
17	HORN - LH / RH <i>new</i>	2	\$	273.00	X
18	HORN BRACKET - LH / RH <i>new</i>	2	\$	66.00	X
19	BONNET <i>Dented</i>	1	\$	3,491.00	✓ 2792.80
20	BONNET ATTACHMENT PARTS <i>new</i>	1	\$	128.00	X
SUB TOTAL SPARE PARTS			:	\$	<u>7,613.00</u>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 791 Y

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET HINGE - LH / RH <i>Neu</i>	2	\$ 932.00	<i>+</i>
22	BONNET IMPACT PROTECTION - LH / RH CENTER <i>Neu</i>	3	\$ 93.00	<i>✓</i> 73.20
23	BONNET SOUND ABSORBER <i>Neu</i>	1	\$ 382.00	<i>+</i>
24	BONNET BOWDEN CABLE - CENTER <i>Damaged</i>	1	\$ 50.56	<i>64.00</i> <i>✓</i> <i>3 fls.</i>
25	BONNET RELEASE LEVER <i>Damaged</i>	1	\$ 11.84	<i>15.00</i> <i>✓</i>
26	BONNET BOWDEN CABLE - CENTER <i>Neu</i>	1	\$ 64.00	<i>+</i>
27	BONNET BOWDEN CABLE COVER <i>Neu</i>	1	\$ 11.00	<i>+</i>
28	BONNET STRIKER - LH / RH	2	\$ 112.00	<i>+</i>
29	BONNET LOCK <i>Neu</i>	2	\$ 455.00	<i>+</i>
30	HEADLIGHT LH RH <i>Cracked, LH Trashed</i>	2	\$ 16,832.00	<i>8416</i> <i>16832 fls.</i> <i>13,465.60</i>
31	HEADLIGHT LIFT CYLINDER - LH / RH <i>Neu</i>	2	\$ 434.00	<i>+</i>
32	HEADLIGHT LIFT CYLINDER BRACKET - LH / RH <i>Neu</i>	2	\$ 34.00	<i>+</i>
33	HEADLIGHT LIFT CYLINDER CORRUGATED PIPE <i>Neu</i>	1	\$ 100.00	<i>+</i>
34	LOCK CARRIER <i>Neu</i>	1	\$ 1,127.00	<i>+</i> <i>?</i> <i>X</i>
35	LOCK CARRIER SUPPORT <i>Neu</i>	2	\$ 85.00	<i>?</i> <i>X</i>
36	A/C CONDENSER <i>Dented</i>	1	TBC	<i>546</i> <i>3 fls.</i>
37	A/C BRACKET <i>Damaged</i>	1	\$ 21.00	<i>16.32</i> <i>✓</i>
38	CHARGE AIR COOLER <i>Neu</i>	1	\$ 654.00	<i>+</i>
39	PRESSURE HOSE <i>Neu</i>	1	\$ 413.00	<i>+</i>
40	PRESSURE PIPE <i>Neu</i>	1	\$ 496.00	<i>+</i>
SUB TOTAL SPARE PARTS			\$ 22,324.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

AIG - Adnan - 4 days



LA/

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 791 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR <i>Not in</i>	1	\$ 1,010.00	+
42	COOLANT <i>Not in</i>	6	\$ 282.00	7 X
43	RADIATOR FAN <i>Not in</i>	1	\$ 2,483.00	+
44	RADIATOR AIR GUIDE (LH/RH) UPPER / LOWER <i>Not in</i>	1	\$ 154.00	✓ <i>H/S</i> 85.84
45	RADIATOR FAN RING <i>Not in</i>	1	\$ 291.00	+
46	LOWER NOISE INSULATION <i>Not in</i>	1	\$ 640.00	+
47	FRONT NO. PLATE <i>Not in</i>	S/N	\$ 60.00	✓ 60
48	SUNDRIES <i>Not in</i>		\$ 350.00	? 10.24
TOTAL SPARE PARTS		:	\$ 35,207.00	
TOTAL LABOUR CHARGES		:	\$ 10,472.00	
GRAND TOTAL		:	\$ 45,679.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.