

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/364/2022/TF
DATE : 10-May-22
WIP : 23100

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/5/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR GOH TOH HAI
ADDRESS : BLK 359 WOODLANDS AVE 5
#04-366
SINGAPORE 730359
TELEPHONE : HP +65 98288384
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMN 791 Y**
MODEL CODE : A5 SPORTBACK 2.0 TFSI S tronic
MODEL YEAR : 24/7/2019
ENGINE NO : CVK 084568
CHASSIS NO : WAUZZZF55KA061245
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-May-22
PLACE OF ACCIDENT : ALONG CTE TOWARDS WOODLANDS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 791 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	250
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	S/N \$ 1,700.00	?
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. BONNET AND BOTH HEADLIGHT. POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1000
5	TO APPLY PROTECTION FILM ON HEADLIGHT AND PAINT COATING AT AFFECTED AREA. (BY OWNER	S/N TBC	?
6	TO RESPRAY FRONT BUMPER, BONNET AND HINGES. ✓	\$ 2,500.00	1100
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,472.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 791 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Debond</i>	1	TBC	✓
2	FRONT BUMPER RADIATOR GRILLE <i>Smashed</i>	1	TBC	✓
3	FRONT BUMPER AIR GRILLE - LH / RH <i>RH cracked</i>	2	TBC	✓
4	FRONT BUMPER FOAM <i>not new</i>	1	\$ 139.00	+
5	FRONT BUMPER CARRIER <i>Dented</i>	1	\$ 899.00	✓
6	FRONT BUMPER TOP COVER <i>Debond</i>	1	\$ 143.00	✓
7	CAUTION STICKER <i>?</i>	1	\$ 16.00	✓
8	A/C STICKER <i>new</i>	1	\$ 9.00	✓
9	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 82.00	+
10	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$ 508.00	?
11	FRONT BUMPER CARRIER BRACKET <i>cracked ?</i>	1	\$ 154.00	?
12	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 64.00	?
13	RIVET <i>new</i>	4	\$ 4.00	✓
14	FRONT BUMPER PARKING AID SENSOR - INNER / OUTER <i>not new</i>	4	\$ 1,060.00	+
15	FRONT BUMPER PARKING AID SENSOR SEAL RING <i>?</i>	4	\$ 10.00	?
16	FRONT BUMPER WIRING SET <i>new</i>	1	\$ 567.00	+
17	HORN - LH / RH <i>new</i>	2	\$ 273.00	+
18	HORN BRACKET - LH / RH <i>new</i>	2	\$ 66.00	+
19	BONNET <i>Dented</i>	1	\$ 3,491.00	✓
20	BONNET ATTACHMENT PARTS <i>not new</i>	1	\$ 128.00	+
SUB TOTAL SPARE PARTS		:	\$ 7,613.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 791 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET HINGE - LH / RH <i>new</i>	2	\$ 932.00	<i>x</i>
22	BONNET IMPACT PROTECTION - LH / RH CENTER <i>new</i>	3	\$ 93.00	<i>✓</i>
23	BONNET SOUND ABSORBER <i>new</i>	1	\$ 382.00	<i>x</i>
24	BONNET BOWDEN CABLE - CENTER <i>new</i>	1	\$ 64.00	<i>x</i>
25	BONNET RELEASE LEVER	1	\$ 15.00	<i>x</i>
26	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	<i>x</i>
27	BONNET BOWDEN CABLE COVER	1	\$ 11.00	<i>x</i>
28	BONNET STRIKER - LH / RH	2	\$ 112.00	<i>x</i>
29	BONNET LOCK <i>new</i>	2	\$ 455.00	<i>x</i>
30	HEADLIGHT - LH / RH <i>RA cancelled, LH?</i>	2	\$ 16,832.00	<i>8416.</i>
31	HEADLIGHT LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 434.00	<i>x</i>
32	HEADLIGHT LIFT CYLINDER BRACKET - LH / RH <i>new</i>	2	\$ 34.00	<i>x</i>
33	HEADLIGHT LIFT CYLINDER CORRUGATED PIPE <i>new</i>	1	\$ 100.00	<i>x</i>
34	LOCK CARRIER <i>new?</i>	1	\$ 1,127.00	<i>x?</i>
35	LOCK CARRIER SUPPORT <i>?</i>	2	\$ 85.00	<i>?</i>
36	A/C CONDENSER	1	TBC	<i>x</i>
37	A/C BRACKET	1	\$ 21.00	<i>x</i>
38	CHARGE AIR COOLER	1	\$ 654.00	<i>x</i>
39	PRESSURE HOSE	1	\$ 413.00	<i>x</i>
40	PRESSURE PIPE	1	\$ 496.00	<i>x</i>
SUB TOTAL SPARE PARTS		:	\$ 22,324.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 791 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR <i>new</i>	1	\$ 1,010.00	<i>+</i>
42	COOLANT <i>?</i>	6	\$ 282.00	<i>?</i>
43	RADIATOR FAN <i>new</i>	1	\$ 2,483.00	<i>+</i>
44	RADIATOR AIR GUIDE - LH / RH / UPPER / LOWER <i>?</i>	6	\$ 154.00	<i>?</i>
45	RADIATOR FAN RING <i>new</i>	1	\$ 291.00	<i>+</i>
46	LOWER NOISE INSULATION <i>new</i>	1	\$ 640.00	<i>+</i>
47	FRONT NO. PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓</i>
48	SUNDRIES <i>?</i>		\$ 350.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 35,207.00	
TOTAL LABOUR CHARGES		:	\$ 10,472.00	
GRAND TOTAL		:	\$ 45,679.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian

SURVEYED DATE

: 10/05/22

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 04 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT