



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM21007886/Rqy3-1

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Ref: ~~CS3/ASM21007886/R1gc~~  
Date: ~~23/07/2021~~ 31/03/2022  
Code: ASM

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 8178H	Veh. Inspected	FBH 3847M
Policy No.		Coverage (\$)	0.00
Claim No.	<del>SHM03E03</del> 22.29547	Excess (\$)	0.00
Assign From	<del>TEO KITT</del> HENG XIN YI(SEAH ONG)	Assign Date	<del>23/07/2021</del> 31/03/2022

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	18/07/2021	Inspection Date	26/07/2021
Survey held at	AH HWA MOTOR SERVICING 1016 YISHUN INDUSTRIAL PARK A, #01-228, YISHUN INDUSTRIAL PARK A, SINGAPORE 768758		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.