

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TM122004400/TTCN2**Date:** 03/06/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS007968	
Claimant Vehicle No :	SHD3482G	Insured Vehicle No :	SJU750P	
Date of Loss:	09/05/2022	Nature of Claim:	TP	Claim No: M2202273

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3482G	Engine No:	G4LEKU411464
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU190519
Reg. Date:	18/03/2020 (Man. Year: 2019)	Odometer:	248048 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,688.22	433.60	1,254.62	74.32
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,020.00	630.00	390.00	38.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,719.22	1,074.60	1,644.62	60.48
+ GST 7.00/7.00% (S\$)	190.35	75.22	115.13	60.48
Nett Amount (S\$)	2,909.57	1,149.82	1,759.75	60.48

INSPECTION

Date of Assignment:	10/05/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/05/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jun 2022)

Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD3482G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	-	*451.25 FL
2	1		*REAR BUMPER	Repair	459.40 FL	-	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	-	*- FL
4	10		*REAR BUMPER CLIP	Necessary	22.00 FL	-	*22.00 FL
5	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	111.60 FL	-	*- FL
6	1		*REVERSE SENSOR	Not Necessary	180.00 FL	-	*- FL
7	1		*REAR NUMBER PLATE W/HOLDER	Cracked	55.00 FS	-	*55.00 FS
8	1		*REAR FOG LAMP	Not Necessary	201.50 FS	-	*- FS
9	2		*REAR NUMBER LAMP LH/RH	Not Necessary	170.60 FL	-	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,046.15	528.25
- List Item Discount on L Items 20.00/20.00% (\$\$)	357.93	94.65
Total Parts (\$\$)	1,688.22	433.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	CHECK LIGHTING AND WIRING	New	60.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			1,020.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >