

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/365/2022/GW
DATE : 10-May-22
WIP :

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS PUVANESWARI SANDIRASEKARAN
ADDRESS : 80 LORONG M TELOK KURAU
#03-36
SINGAPORE 425414
TELEPHONE : HP +65 90692143
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 721010932
VEHICLE NO : SMZ 7626 H
MODEL CODE : A5 SPORTBACK 2.0 TFSI S tronic
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 084387
CHASSIS NO : WAUZZZF45KA087920
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-May-22
PLACE OF ACCIDENT : JOO CHIAT LN & TEMBELING RD , SINGAPORE

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 7626 H- FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WHASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MOUDLE.	S/N \$ 350.00 250	
3	TO REMOVE AND TRANSFER LHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00 560	
4	TO RENEW LHS FRONT FENDER INNER PIPES. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 280.00 9 /	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. 4 X 500	\$ 4,200.00 2000	
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE AND LHS REAR DOOR. 550 X 5 + 150 + 180	\$ 5,000.00 2980	
7	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00 2 /	
8	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00 /	
SUB TOTAL LABOUR CHARGES		: \$ 13,930.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 7626 H - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AND REAR LID KICK SENSOR.	S/N \$ 360.00 /	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LHS FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,400.00 750 1.5 X \$00	
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER.	\$ 2,000.00 1100 \$50 X 2	
4	TO RENEW LHS REAR RIM.	S/N \$ 40.00 X	
5	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 X	
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 /	
TOTAL LABOUR CHARGES		: \$ 18,394.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER / <i>cm</i>	1	TBC	<i>1479-601</i>
2	FRONT BUMPER FIXING PARTS <i>X nn</i>	1	\$	612.00
3	FRONT BUMPER AIR GUIDE - LH <i>? X nn</i>	1	\$	72.00
4	FRONT BUMPER SECURING STRIP <i>X nn</i>	2	\$	79.00
5	FRONT BUMPER GRILLE - CENTER <i>X nn</i>	1	\$	219.00
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ <i>X nn</i>	254.00
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>? X nn</i>	1	\$	151.00
8	FRONT BUMPER GUIDE SECTION - LH <i>? BR</i>	1	\$	41.00 / <i>32.24</i>
9	FRONT BUMPER COVER <i>X nn</i>	1	\$	143.00
10	STICKER FOR 'SIGN CAUTION' <i>X nn</i>	1	\$	16.00
11	SITCKER FOR AIR CONDITIONER <i>X nn</i>	1	\$	9.00
12	FRONT FENDER - LH <i>nn</i>	1	\$	861.00 / <i>688.80</i>
13	FRONT FENDER ATTACHMENT PARTS <i>? X nn</i>	1	\$	211.00
14	FRONT FENDER CLOSING ELEMENT - LH <i>nn</i>	1	\$	81.00 / <i>64.24</i>
15	FRONT FENDER CENTER BRACKET - LH <i>nn</i>	1	\$	41.00 / <i>32.72</i>
16	FRONT FENDER BRACKET FOR DEFORMATION - LH <i>nn</i>	1	\$	55.00 / <i>44.00</i>
17	FRONT FENDER POP RIVET <i>nn</i>	6	\$	23.00 / <i>18.24</i>
18	FRONT FENDER REAR BRACKET - LH <i>X nn</i>	1	\$	36.00
19	FRONT FENDER UPPER BRACKET - LH <i>? X nn</i>	1	\$	37.00
20	FRONT FENDER BRACE - LH <i>? / DD</i>	1	\$	132.00 / <i>105.20</i>
SUB TOTAL SPARE PARTS			\$	<u>3,073.00</u>

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER INSULATOR - LH ? X nn	1	\$ 37.00	
22	FRONT FENDER COVER - LH ? X nn	1	\$ 13.00	
23	FRONT WHEEL HOUSING LINER - LH ? / CRU	1	\$ 260.00	208
24	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH ? X nn	1	TBC	
25	FRONT WHEEL SPOILER - LH / OR	1	\$ 82.00	65.12
26	FRONT END PLATE - LH ? X nn	1	\$ 39.00	
27	FRONT STONE CHIP GUARD - LH / CRU	1	\$ 57.00	45.28
28	FRONT FENDER LEDGE COVER LONG - LH / n2	1	\$ 35.00	27.52
29	FRONT FENDER LEDGE COVER SHORT - LH / n2	1	\$ 26.00	20.16
30	BONNET X R	1	\$ 3,425.00	
31	BONNET IMPACT PROTECTION - CENTER X nn	1	\$ 31.00	
32	BONNET IMPACT PROTECTION - LH / RH X nn	2	\$ 62.00	
33	FRONT DOOR - LH / M	1	\$ 3,431.00	2744.80
34	FRONT OUTER SEAL - LH / n2	1	\$ 229.00	182.80
35	BONDING AGENT / X nn	1	\$ 51.00	
36	CLEANING SOLUTION X n2 nn	1	\$ 74.00	
37	APPLICATOR X nn	1	\$ 8.00	
38	FRONT DOOR ATTACHMENT PARTS - LH X nn	1	\$ 1,153.00	
39	FRONT DOOR CATCH - LH ? X nn	1	TBC	
40	FRONT DOOR TRIM PLATE - LH X R	1	\$ 98.00	
SUB TOTAL SPARE PARTS			\$ 9,111.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.


55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT DOOR HANDLE COVER CAP - LH <i>X R</i>	1	\$	7.00	
42	FRONT DOOR HANDLE HOUSING - LH <i>X nn</i>	1	\$	9.00	
43	FRONT EXTERIOR MIRROR MOUNTING - LH <i>/ [nt]</i>	1	\$	1,201.00	<i>960.80</i>
44	FRONT WING MIRROR CAP - LH <i>X R</i>	1	\$	308.00	
45	FRONT WING MIRROR GLASS - LH <i>X nn</i>	1	\$	1,298.00	
46	FRONT WINDOW SLOT SEAL - LH <i>X nn</i>	1	\$	344.00	
47	ASSEMBLY CARRIER <i>? X nn</i>	1	\$	2,096.00	
48	FRONT WISHBONE LINK - LH <i>? / BT</i>	1	\$	605.00	<i>483.60</i>
49	FRONT SUSPENSION LINK - LH <i>? / BT</i>	1	\$	1,057.00	<i>845.60</i>
50	FRONT CONTROL ARM - LH <i>? X nn</i>	1	\$	575.00	
51	FRONT CONTROL ARM REAR - LH <i>? X nn</i>	1	\$	575.00	
52	FRONT WHEEL BEARING HOUSING - LH <i>? / BT</i>	1	\$	5,070.00	<i>856</i>
53	SWIVEL JOINT <i>? / nec</i>	1	\$	214.00	<i>170.80</i>
54	FRONT WHEEL HUB - LH <i>? / nec</i>	1	\$	498.00	<i>398</i>
55	FRONT BALL BEARING - LH <i>? / nec</i>	1	\$	273.00	<i>218</i>
56	FRONT SUSPENSION FORKS - LH <i>? / BT</i>	1	\$	293.00	<i>234</i>
57	FRONT COUPLING ROD <i>? X nn</i>	2	\$	258.00	
58	FRONT DRIVE SHAFT <i>? X nn</i>	1	\$	2,999.00	
59	FRONT GAS SHOCK ABSORBER - LH <i>? X nn</i>	1	\$	332.00	
60	FRONT TRACK ROD <i>? X nn</i>	1	\$	109.00	
			:	\$	18,121.00

SUB TOTAL SPARE PARTS

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT STEERING GEAR ? X nn	1	\$ 7,318.00	
62	LED HEADLIGHT - LH ? X nn	1	TBC	
63	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM ? X nn	1	\$ 231.00	
64	CORRUGATED PIPE FOR HEADLIGHT WASHER SYSTEM ?	1	\$ X nn 107.00	
65	CORRUGATED PIPE BRACKET ? X nn	1	\$ 7.00	
66	FRONT NOISE INSULATION ? X nn	1	\$ 640.00	
67	A/C PIPE ? BT	1	\$ 585.00	468.00
68	A/C PIPE BRACKET ? X nn	1	\$ 9.00	
69	A/C DISCHARGE HOSE ? X nn	1	\$ 381.00	
70	A/C SUCTION HOSE ? X nn	1	\$ 277.00	
71	A/C LINE ? X nn	1	\$ 186.00	
72	FRONT RIM - LH full X R	1	TBC	
73	FRONT TYRE - LH 1 / TN (80%)	1	TBC	2801
SUB TOTAL SPARE PARTS			\$ 40,046.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699


TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
74	REAR DOOR - LH <i>OK</i>	1	\$	3,431.00 / 2744.80	
75	REAR DOOR OUTER SEAL - LH <i>OK</i>	1	\$	229.00 / 182.80	
76	BONDING AGENT <i>X OK</i>	1	\$	51.00	
77	CLEANING SOLUTION <i>OK</i>	1	\$	74.00	
78	APPLICATOR <i>X OK</i>	1	\$	8.00	
79	REAR DOOR ATTACHMENT PARTS <i>X OK</i>	1	\$	943.00	
80	REAR DOOR CATCH - RH <i>?</i>	1		TBC	
81	REAR BUMPER <i>X R</i>	1	\$	3,188.00	
82	REAR BUMPER SECURING STRIP <i>X OK</i>	1	\$	249.00	
83	REAR BUMPER GUIDE SECTION - LH / RH <i>X OK</i>	2	\$	52.00	
84	REAR BUMPER UPPER GUIDE SECTION - LH <i>X OK</i>	1	\$	49.00	
85	REAR RIM - LH <i>X OK</i>	1		TBC	
86	SUNDRIES <i>?</i>	1	\$	700.00	<i>183-20</i>
TOTAL SPARE PARTS (FRONT & REAR)		:	\$	49,020.00	
TOTAL LABOUR CHARGES (FRONT & REAR)		:	\$	18,394.00	
GRAND TOTAL		:	\$	67,414.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
11/5/22, 10.30am

DD- M AL
EXcess - 2
P/P
17 ~~17~~ dys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0365/2022/GW
18-May-22
CHANG
1 of 1
SMZ 7626 H
AUDI A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO RESPRAY LHS SILL PANEL.	\$ 1,400.00	550
Parts			
1	STONE CHIP <i>✓ nec</i> S/N	\$ 180.00	
GRAND TOTAL		\$ 1,580.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Sten (LKK)
18/5/22