

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0365/2022/GW
DATE : 10-May-22
WIP :

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/5/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

17 days exclude 3 Sundays

Johnny Boo 20 Jul 22

OWNER'S NAME : MS PUVANESWARI SANDIRASEKARAN
ADDRESS : 80 LORONG M TELOK KURAU
#03-36
SINGAPORE 425414
TELEPHONE : HP +65 90692143
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 721010932
VEHICLE NO : **SMZ 7626 H**
MODEL CODE : A5 SPORTBACK 2.0 TFSI S tronic
MODEL YEAR : 30/9/2019
ENGINE NO : CVK 084387
CHASSIS NO : WAUZZZF45KA087920
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-May-22
PLACE OF ACCIDENT : JOO CHIAT LN & TEMBELING RD , SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 7626 H- FRONT

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WHASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MOUDLE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND TRANSFER LHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$	560.00
4	TO RENEW LHS FRONT FENDER INNER PIPES. TO CARRY OUT VACUUM AND REGAS.	S/N \$	280.00	\$	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR , LHS REAR DOOR AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	\$	2,000.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE AND LHS REAR DOOR.	\$	5,000.00	\$	2,980.00
7	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	\$	2,400.00
8	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$	520.00
SUB TOTAL LABOUR CHARGES		:	\$ 13,930.00	\$	9,470.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 7626 H - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 9,470.00
1	TO REMOVE AND TRANSFER REAR PARKING AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LHS FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	\$ 750.00
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER.	\$	2,000.00	\$ 1,100.00
4	TO RENEW LHS REAR RIM.	S/N \$	40.00	
5	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	
6	Added labour - see attached	\$	1,400.00	\$ 550.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 19,794.00	\$ 12,614.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,787.00	\$	1,429.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00		
3	FRONT BUMPER AIR GUIDE - LH	1	\$ 72.00		
4	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
5	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00		
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00		
8	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	\$	32.24
9	FRONT BUMPER COVER	1	\$ 143.00		
10	STICKER FOR ' SIGN CAUTION '	1	\$ 16.00		
11	SITCKER FOR AIR CONDITIONER	1	\$ 9.00		
12	FRONT FENDER - LH	1	\$ 861.00	\$	688.80
13	FRONT FENDER ATTACHMENT PARTS	1	\$ 211.00		
14	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 81.00	\$	64.24
15	FRONT FENDER CENTER BRACKET - LH	1	\$ 41.00	\$	32.72
16	FRONT FENDER BRACKET FOR DEFORMATION - LH	1	\$ 55.00	\$	44.00
17	FRONT FENDER POP RIVET	6	\$ 23.00	\$	18.24
18	FRONT FENDER REAR BRACKET - LH	1	\$ 36.00		
19	FRONT FENDER UPPER BRACKET - LH	1	\$ 37.00		
20	FRONT FENDER BRACE - LH	1	\$ 132.00	\$	105.20
SUB TOTAL SPARE PARTS		:	\$ 4,860.00	\$	2,415.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>2,415.04</i>
21	FRONT FENDER INSULATOR - LH	1	\$ 37.00		
22	FRONT FENDER COVER - LH	1	\$ 13.00		
23	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	<i>\$</i>	<i>208.00</i>
24	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH	1	TBC		
25	FRONT WHEEL SPOILER - LH	1	\$ 82.00	<i>\$</i>	<i>65.12</i>
26	FRONT END PLATE - LH	1	\$ 39.00		
27	FRONT STONE CHIP GUARD - LH	1	\$ 57.00	<i>\$</i>	<i>45.28</i>
28	FRONT FENDER LEDGE COVER LONG - LH	1	\$ 35.00	<i>\$</i>	<i>27.52</i>
29	FRONT FENDER LEDGE COVER SHORT - LH	1	\$ 26.00	<i>\$</i>	<i>20.16</i>
30	BONNET	1	\$ 3,425.00		
31	BONNET IMPACT PROTECTION - CENTER	1	\$ 31.00		
32	BONNET IMPACT PROTECTION - LH / RH	2	\$ 62.00		
33	FRONT DOOR - LH	1	\$ 3,431.00	<i>\$</i>	<i>2,744.80</i>
34	FRONT OUTER SEAL - LH	1	\$ 229.00	<i>\$</i>	<i>182.80</i>
35	BONDING AGENT	1	\$ 51.00		
36	CLEANING SOLUTION	1	\$ 74.00		
37	APPLICATOR	1	\$ 8.00		
38	FRONT DOOR ATTACHMENT PARTS - LH	1	\$ 1,153.00		
39	FRONT DOOR CATCH - LH	1	TBC		
40	FRONT DOOR TRIM PLATE - LH	1	\$ 98.00		
SUB TOTAL SPARE PARTS			\$ 9,111.00	<i>\$</i>	<i>5,708.72</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>5,708.72</i>
41	FRONT DOOR HANDLE COVER CAP - LH	1	\$ 7.00		
42	FRONT DOOR HANDLE HOUSING - LH	1	\$ 9.00		
43	FRONT EXTERIOR MIRROR MOUNTING - LH	1	\$ 1,201.00	<i>\$</i>	<i>960.80</i>
44	FRONT WING MIRROR CAP - LH	1	\$ 308.00		
45	FRONT WING MIRROR GLASS- LH	1	\$ 1,298.00		
46	FRONT WINDOW SLOT SEAL - LH	1	\$ 344.00		
47	ASSEMBLY CARRIER	1	\$ 2,096.00		
48	FRONT WISHBONE LINK -LH	1	\$ 605.00	<i>\$</i>	<i>483.60</i>
49	FRONT SUSPENSION LINK - LH	1	\$ 1,057.00	<i>\$</i>	<i>845.60</i>
50	FRONT CONTROL ARM - LH	1	\$ 575.00		
51	FRONT CONTROL ARM REAR - LH	1	\$ 575.00		
52	FRONT WHEEL BEARING HOUSING - LH	1	\$ 1,070.00	<i>\$</i>	<i>856.00</i>
53	SWIVEL JOINT	1	\$ 214.00	<i>\$</i>	<i>170.80</i>
54	FRONT WHEEL HUB - LH	1	\$ 498.00	<i>\$</i>	<i>398.00</i>
55	FRONT BALL BEARING - LH	1	\$ 273.00	<i>\$</i>	<i>218.00</i>
56	FRONT SUSPENSION FORKS - LH	1	\$ 293.00	<i>\$</i>	<i>234.00</i>
57	FRONT COUPLING ROD	2	\$ 258.00		
58	FRONT DRIVE SHAFT	1	\$ 2,999.00		
59	FRONT GAS SHOCK ABSORBER - LH	1	\$ 332.00		
60	FRONT TRACK ROD	1	\$ 109.00		
SUB TOTAL SPARE PARTS			:	\$ 14,121.00	<i>\$ 9,875.52</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>9,875.52</i>
61	FRONT STEERING GEAR	1	\$ 7,318.00		
62	LED HEADLIGHT - LH	1	TBC		
63	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	1	\$ 231.00		
64	CORRUGATED PIPE FOR HEADLIGHT WASHER SYSTEM	1	\$ 107.00		
65	CORRUGATED PIPE BRACKET	1	\$ 7.00		
66	FRONT NOISE INSULATION	1	\$ 640.00		
67	A/C PIPE	1	\$ 585.00	<i>\$</i>	<i>468.00</i>
68	A/C PIPE BRACKET	1	\$ 9.00		
69	A/C DISCHARGE HOSE	1	\$ 381.00		
70	A/C SUCTION HOSE	1	\$ 277.00		
71	A/C LINE	1	\$ 186.00		
72	FRONT RIM - LH	1	TBC		
73	FRONT TYRE - LH @80%	1	<i>\$ 350.00</i>	<i>\$</i>	<i>280.00</i>
SUB TOTAL SPARE PARTS		:	\$ 38,183.00	\$	<i>10,623.52</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7626 H - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 10,623.52</i>
74	REAR DOOR - LH	1	\$ 3,431.00	<i>\$ 2,744.80</i>
75	REAR DOOR OUTER SEAL - LH	1	\$ 229.00	<i>\$ 182.80</i>
76	BONDING AGENT	1	\$ 51.00	
77	CLEANING SOLUTION	1	\$ 74.00	
78	APPLICATOR	1	\$ 8.00	
79	REAR DOOR ATTACHMENT PARTS	1	\$ 943.00	
80	REAR DOOR CATCH - RH	1	TBC	
81	REAR BUMPER	1	\$ 3,188.00	
82	REAR BUMPER SECURING STRIP	1	\$ 249.00	
83	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 52.00	
84	REAR BUMPER UPPER GUIDE SECTION - LH	1	\$ 49.00	
85	REAR RIM - LH	1	TBC	
85a	ADDED PARTS - SEE ATTACHED	S/N	\$ 180.00	<i>\$ 180.00</i>
87	SUNDRIES	1	\$ 700.00	<i>\$ 183.20</i>
TOTAL SPARE PARTS (FRONT & REAR)		:	\$ 47,337.00	<i>\$ 13,914.32</i>
TOTAL LABOUR CHARGES (FRONT & REAR)		:	\$ 19,794.00	<i>\$ 12,614.00</i>
GRAND TOTAL		:	\$ 67,131.00	<i>\$ 26,528.32</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-01/07/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0365/2022/GW 18-May-22 CHANG 1 of 1 SMZ 7626 H AUDI A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO RESPRAY LHS SILL PANEL.	\$ 1,400.00	\$ 550.00
<u>Parts</u>			
1	STONE CHIP S/N	\$ 180.00	\$ 180.00
GRAND TOTAL		\$ 1,580.00	\$ 730.00

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT