



Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986
HP: 98888885

7TDZS3EU00J067903

TP ECICS
VERON.

Date:	10/5/2022
Vehicle:	SNE3509M
Make / Model:	TOYOTA PRIUS
Chassis:	ECICS

No.	Description	Unit	Unit Price	Amount
1	TAILGATE <i>Dented</i>	1	\$ 1,598.00	\$ <u>1,598.00</u>
2	TAILGATE LAMP <i>new</i>	2	\$ 459.00	\$ 918.00
3	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 212.00	\$ 212.00
4	TAILGATE LOGO <i>new</i>	1	\$ 95.50	\$ 95.50
5	TAILGATE EMBLEM PRIUS t <i>3/4"</i>	1	\$ 89.40	\$ 89.40
6	TAILGATE EMBLEM HYBRID	1	\$ 82.30	\$ 82.30
7	TAILGATE DETECTOR <i>not in</i>	1	\$ 321.00	\$ 321.00
8	TAILGATE LOCK <i>new</i>	1	\$ 312.00	\$ 312.00
9	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 198.00	\$ 198.00
10	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 459.00	\$ 459.00
11	REAR BUMPER <i>Distorted</i>	1	\$ 798.00	\$ 798.00
12	REAR BUMPER SIDE RETAINER <i>LH 2nd</i>	2	\$ 112.00	\$ 224.00
13	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 422.00	\$ 422.00
14	REAR BUMPER BRACKET <i>new</i>	2	\$ 114.00	\$ 228.00
15	REAR BUMPER LIP <i>Dented</i>	1	\$ 728.90	\$ <u>728.90</u>
16	REAR BUMPER REFLECTOR LH <i>crushed</i>	1	\$ 68.00	\$ 68.00
17	REAR BUMPER UNDER COVER LH <i>new</i>	1	\$ 321.00	\$ 321.00
18	REAR FENDER LH <i>Reps</i>	1	\$ 698.00	\$ 698.00
19	REAR FENDER COWLING LH <i>torn</i>	1	\$ 198.20	\$ 198.20
20	REAR FENDER INNER TRIM (LOWER) LH <i>new</i>	1	\$ 612.00	\$ 612.00
21	TAILAMP LH <i>Smashed</i>	1	\$ 694.00	\$ <u>694.00</u>
22	TAILAMP LOWER BRACKET LH <i>crushed</i>	1	\$ 82.00	\$ 82.00
23	TAILAMP LOWER PANEL LH <i>Dented</i>	1	\$ 314.00	\$ 314.00
24	REAR END PANEL <i>Dented</i>	1	\$ 612.00	\$ 612.00
25	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 212.00	\$ 212.00
26	REAR FLOOR PANEL <i>new</i>	1	\$ 1,151.00	\$ 1,151.00
27	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 398.00	\$ 398.00
28	REAR FLOOR PANEL TOP SIDE SPONGE LH <i>new</i>	1	\$ 312.00	\$ 312.00
29	REAR CHASSIS EXTENSION LH <i>new</i>	1	\$ 325.00	\$ 325.00
				\$ 12,683.30
			Less 20%	\$ 2,536.66
			Total	\$ 10,146.64
	S/Nett items:			
1	REAR BUMPER CLIPS <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR WINDSCREEN SEALANT <i>3/4"</i>	1	\$ 80.00	\$ 80.00
4	REAR WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00
5	REAR FENDER INNER TRIM CLIPS SET <i>new</i>	1	\$ 50.00	\$ 50.00
6	REAR REVERSE SENSOR <i>Damaged</i>	1	\$ 250.00	\$ 250.00
7	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1	\$ 80.00	\$ 80.00

8	REAR END PANEL SEALANT <i>nu</i>	1	\$ 60.00	\$ 60.00	✓
				\$ 1,770.00	
	Labour to: REAR <i>370</i>				
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00	<i>30</i>
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00	<i>50</i>
3	TO REMOVE AND REFIT REAR GLASS	1	\$ 150.00	\$ 150.00	<i>120</i>
4	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	1	\$ 300.00	\$ 300.00	<i>60</i>
5	REMOVE AND RENEW TAILGATE MECHANISM	1	\$ 80.00	\$ 80.00	✓
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	<i>80</i>
7	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00	<i>1000</i>
8	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,400.00	\$ 1,400.00	<i>1000</i>
				\$ 3,830.00	
			Parts Replacement Amount	\$ 11,916.64	
			Total Amount for Labour	\$ 3,830.00	
			Total Amount	\$ 15,746.64	

Admin L
h/s 11/05/22

07 Days

total: 6600.67

h/s: 5250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: