

wheel alignment

REF: C12 / 22004411/K nys

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: Chen Goon
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 869K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 07 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. 09/25 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKV 7513U Yr Regn: 09, 15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toy ESAM 9 Wagon c.c. 2362
 Colour: h. Black A/C: Insured / Std / NI / NA
 Sp. Reading: 102508 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: ACR50 0789196

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rlm / STD / Rlm or _____

Tyre Size: F: 225/50R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear
R/Bal. <u>7</u> mm		R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm		L/Bal. <u>7</u> mm

D.O.A. 28/4/2022 D.O.I. 11/5/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
cls FR & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>6/10/21</u>	<u>Pay @ 13,200 ✓</u>

We will be advising our principal a cost of repair of LS \$13,200.00 before GST with 7 days of repair, subject to their approval.
 (red, \$10078.73, 43%)

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: 7
 Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS, SI	
Fuel	
Others	
TOTAL	

Report Format :

Lump Sum / I.B.I: (\$ _____)

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: China Taiping Insurance (S) Pte Ltd

Accident Date : 28.04.2022

Not Notion
U/Pay \$13,200/2
Recovery After Pains
7 days

Third Party

Policy No: _____

Date: 10.05.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota Estima" Reg. No. SKV7513U Claiming Against Your Insured Veh. No. YM8351U			
1pc	Bonnet		<i>R</i> 675.00 ✓
2pcs	Bonnet Hinges	59.00	<i>B</i> 118.00 ✓
1pc	Bonnet Lock		<i>B/Ta</i> 102.00 ✓
1pc	Bonnet Insulator		<i>Netman</i> 270.00 ✓
7pcs	Bonnet Insulator Clips	3.50	<i>na</i> 24.50 ✓
1pc	Bonnet Rubber Seal		<i>cut</i> 112.80 ✓
1pc	Wiper Arm Nut Cover RH		<i>mit</i> 15.00 ✓
1pc	Wiper Garnish		<i>nd</i> 701.00 ✓
1pc	Wiper Garnish End Cover		<i>mit</i> 43.00 ✓
1pc	Wiper Garnish Rubber Seal		<i>cut</i> 155.00 ✓
2pcs	Headlamps (HID)	<i>ols mit</i> 1,598.00	<i>nls m/cm</i> 3,196.00 ✓
1pc	Grille (Aeras Sport)		<i>mit</i> 670.00 ✓
1pc	Grille Emblem (Aeras Sport)		<i>mit</i> 160.00 ✓
1pc	Grille Top Rubber Seal		<i>mit</i> 115.00 ✓
1pc	Headlamp Wiring Harness		<i>cm/ta</i> 696.00 ✓
1pc	Front Bumper (Aeras Sport)		<i>Bu IDIT</i> 885.00 ✓
15pcs	Front Bumper Clips	3.80	<i>na</i> 57.00 ✓
1pc	Front Bumper Bracket RH		<i>cm</i> 199.00 ✓
1pc	Front Bumper Sponge		<i>su</i> 230.00 X
1pc	Front Bumper Top Retainer RH		<i>cm</i> 58.00 ✓
1pc	Front Bumper Reinforcement		<i>R</i> 491.00 X
1pc	Front Bumper Center Air Grille		<i>pu</i> 465.00 X
1pc	Front Bumper Center Air Grille Chrome Moulding		<i>m/cm</i> 328.00 ✓
1pc	Front Bumper Fog Lamp		<i>mit</i> 445.00 ✓
1pc	Front Bumper Fog Lamp Cover		<i>mit</i> 159.00 ✓
1pc	Front Bumper Corner Retainer RH		<i>mit</i> 72.00 ✓
1pc	Support Panel	<i>1043</i>	<i>Bu IDIT</i> 1,226.00 ✓
1pc	Support Panel Top Garnish		<i>cm</i> 267.00 ✓
1pc	Radiator	<i>2050.50</i>	<i>pu</i> 2,230.00 ✓
1pc	Radiator Top Housing Bracket RH		<i>R</i> 70.00 ✓
1pc	Air Con Condenser		<i>na</i> 1,650.00 X
1pc	Wiper Tank		<i>cm</i> 135.00 ✓
1pc	Wiper Tank Neck Filler Hose		<i>mit</i> 28.00 ✓
1pc	Wiper Tank Motor		<i>cm</i> 274.00 ✓
2pcs	Front Fenders	<i>e 685.90</i>	<i>R</i> 1,550.00 ✓
1pc	Front Fender Shield RH		<i>cm</i> 302.00 ✓
10pcs	Front Fender Shield Clips	3.50	<i>na</i> 35.00 ✓
1pc	Front Fender Protector RH	<i>157-60</i>	<i>m/cm</i> 310.00 ✓
4pcs	Front Fender Protector Clips	4.00	<i>na</i> 16.00 ✓
			C/F 18,535.30

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: China Taiping Insurance (S) Pte Ltd

Accident Date : 28.04.2022

Policy No: Third Party

 Date: 10.05.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Toyota Estima" Reg. No. SKV7513U Claiming Against Your Insured Veh. No. YM8351U			
		CIF	18,535.30
1pc	Front Fender Top Quart Glass	Per 215.00	X
1pc	Front Fender Top Quart Glass Moulding RH	Per 215.00	✓
1pc	Front Fender Top Vertical Garnish Inner	Per 145.00	✓
1pc	Front Fender Inner Panel RH	Per 870.00	X
1pc	Front Wheel Bearing 522	Per 560.00	✓
1pc	Front Shock Absorber	Per 516.00	X
1pc	Front Knuckle Arm	Per 543.00	✓
1pc	Front Lower Arm	Per 570.00	X
1pc	Front Lower Arm Ball Joint	Per 233.00	X
1pc	Headlamp Hid Ballast RH 925	Per 932.00	✓
1pc	Headlamp Hid Bulb RH 310	Per 324.00	✓
			23,658.30
	Less 25%		5,914.58
			17,743.73
	Front Number Plate	168sn Per 45.00	SN X
	Front Tyre RH	Per 280.00	SN 609sn
	Front Wheel Rim	Per 550.00	SN 400sn
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	To Refill Air Con Gas		120.00 1001
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 501
	To Provide Transportation (Towing)	(Bill)	120.00 7001
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 ✓
	To Supply Front Fender Quart Glass Sealant	Per 40.00	✓
	To Supply Front Fender Quart Glass Sealer	Per 20.00	✓
	To Supply Front Fender Quart Glass Fastener	Per 40.00	30sn
	To Replace Fender Glass Moulding		70.00 401
		B/F	19,218.73

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: China Taiping Insurance (S) Pte Ltd

Accident Date : 28.04.2022

Policy No: Third Party

 Date: 10.05.2022

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Estima" Reg. No. SKV7513U Claiming Against Your Insured Veh. No. YM8351U		
		C/F	19,218.73
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		250.00 801
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Conduct High Speed Balancing		80.00 201
	To Dismantle / Replace Wire Harness To Facilitate Repair		150.00 1201
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Inner Panel, Fender Wheel Housing, Front O/S Door, Windscreen Pillar Garnish RH etc. Cnt, Weld Support, Fender Inner Panel And Part Replacement.		1,200.00 8001
	To Respray Affected Areas		1,300.00 12001
	To Reseal Paint Protection (Diamond rite) to Spray Paint Areas		1,000.00 7
		Total :	23,278.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: