

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: WAN.517942.Q(W) Date: 17th Jun 2022

Our Ref: CS1/LAW22004412/Gqy3e2

M/s Riaz LLC

133 New Bridge Road #09-09 Chinatown Point Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMD 97X

INSURED VEHICLE: GBE 1079S ACCIDENT DATE: 07/09/2020

We thank you for your instruction on 11/05/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMD 97X from M/s Cozon Engineers.
- b) Survey report by Infiniti Appraisal Service with colour photographs.
- c) Final Repair Bill of SMD 97X from M/s Garage 13 Pte Ltd.
- d) Singapore Accident Statement of Vehicles SMD 97X and GBE 1079S.
- e) Colour damaged vehicle photographs of SMD 97X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMD 97X Make & Model : BMW 535I

Chassis Number : WBAFR72070C264673

Year of Registration : 2010 Engine Capacity : 2979 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.