

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5519C

Not Withheld
Primary B4 paint
\$ 6271.35

AAD2205-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

06 MAY 2022**SHC5519C**

JTDKB3FU003092160

200303878K

TOYOTA

PRIUS GEN 4

05/05/2022

SJS4363H/CHINA

31/03/2021

PART**LIST**

1 COVER, REAR BUMPER	\$	Bu	485.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	Bu	332.70	✓
1 COVER, REAR BUMPER, LOWER	\$	mis	22.00	✓
1 GUARD, REAR BUMPER, CENTER	\$	Bu	374.50	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	Sm	132.60	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	Sm	132.60	X
1 REFLECTOR ASSY, REFLEX, LH	\$	Sm	39.00	X
1 REFLECTOR ASSY, REFLEX, RH	\$	Sm	39.00	X
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$	Sm	339.60	X
1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	Sm	261.00	X
1 PANEL SUB-ASSY, BACK DOOR	\$	Bu	1,147.80	✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	un	54.60	X
1 PLATE, BACK DOOR NAME, NO.1	\$	un	54.60	X
1 ORNAMENT SUB-ASSY, BACK DOOR	\$	un	47.90	X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	Sm	913.60	X
1 BOARD ASSY, BACK DOOR TRIM	\$	Sm	259.20	X
1 WEATHERSTRIP, BACK DOOR	\$	Sm	372.30	X
1 BOARD, REAR FLOOR, NO.1	\$	Sm	519.00	X
1 BOX, DECK FLOOR, REAR	\$	Sm	105.80	X
1 BOX, DECK FLOOR, RH	\$	Sm	313.60	X
1 BOX, DECK FLOOR, LH	\$	Sm	313.00	X
1 PAN, REAR FLOOR	\$	R	583.40	X
1 COVER, FLOOR UNDER, NO.1 LH	\$	Sm	175.10	X
1 COVER, FLOOR UNDER, NO.2 RH	\$	Sm	241.90	X
1 COVER, REAR FLOOR CTR	\$	mis	229.90	✓
1 COVER, DECK TRIM, REAR	\$	Sm	126.70	X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	Bu	651.00	✓

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5519C

1 STAY ASSY, BACK DOOR, LH	\$	Sh	242.50	X
1 STAY ASSY, BACK DOOR, RH	\$	Sh	242.50	X
1 HINGE ASSY, BACK DOOR, LH	\$	R	61.00	X
1 HINGE ASSY, BACK DOOR, RH	\$	R	61.00	X
1 COVER, FRONT BUMPER	\$	Bu	521.00	✓
1 COVER, FRONT BUMPER HOLE, LH	\$	mi	30.20	✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	Sh	110.50	X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	R	716.60	X
1 ABSORBER, FRONT BUMPER ENERGY	\$	CM	80.20	✓
1 GRILLE SUB-ASSY, RADIATOR	\$	mi	422.50	✓
1 GRILLE, RADIATOR, LOWER NO.1	\$	na	178.60	✓
1 EMBLEM ASSY, RADIATOR GRILLE	\$	na	105.80	✓
TOTAL	\$		11,040.40	
25%	\$		2,760.10	
	\$		8,280.30	

Special Nett

1SET PARKING AID	\$	na	700.00	2205a
1SET REAR BUMPER CLIP	\$	na	95.00	605a
2 WINDSCREEN SEALANT	\$	na	150.00	805a
1 WINDSCREEN MOULDING	\$	na	200.00	✓
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	305a
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	X
1 REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	X
1 REAR BUMPER PROTECTOR	\$	na	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	X
1 END PANEL TRIM CLIP	\$	na	65.00	X
1SET BUMPER CLIP FRT	\$	na	95.00	605a
1 FRONT NUMBER PLATE WITH MOULDING	\$	na	200.00	455a
1SET FRNT BUMPER RETAINER CLIP	\$	na	85.00	X
TOTAL	\$		2,145.00	

TOTAL PARTS \$ 10,425.30**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 180a

Trans-cab Auto Services Pte Ltd**AAD2205-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5519C

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	8001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	8801
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	301

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5519C

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 220.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ *nn* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *nn* 380.00 X**TOTAL** \$ **9,300.00****Over All Total** \$ **19,725.30****(PART-BY-PART) Repair Days**~~25 DAYS~~*7 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: