

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004423/TQY3E2

Date: 21/07/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00090192101		
Claimant Vehicle No :	SLF8836D	Insured Vehicle No :	SJX1229G		
Date of Loss:	08/05/2022	Nature of Claim:	TP	Claim No:	SNM22D203180/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF8836D	Engine No:	274AE093135A
Make & Model:	INFINITI Q50, 2.0 T (R18) EU6 NAV (A)	Chassis No:	JN1BCAV37Z0570085
Reg. Date:	30/07/2018 (Man. Year: 2017)	Odometer:	47237 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,898.20	905.94	1,992.26	68.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,698.00	2,098.00	1,600.00	43.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,596.20	3,003.94	3,592.26	54.46
+ GST 7.00/7.00% (S\$)	461.73	210.28	251.45	54.46
Nett Amount (S\$)	7,057.93	3,214.22	3,843.71	54.46

INSPECTION

Date of Assignment:	11/05/2022		
Date Inspected:	04/07/2022	Inspected At:	Wearnes Automotive Pte Ltd (Leng Kee) 45 Leng Kee Road Singapore 159103
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2022)
Parts:	143	INFINITI Q50 2.0 T (R18) EU6 NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF8836D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SET FR	Repair	1,213.10 FS	*- FS
2	1		*CLIP RH	Not Necessary	105.30 FS	*- FS
3	1		*CLIP LH	Not Necessary	105.30 FS	*- FS
4	1		*BUMPER FRT RETAINER	Not Necessary	117.10 FS	*- FS
5	1		*BUMPER FRT RETAINER	Not Necessary	117.10 FS	*- FS
6	10		*BUMPER CLIP FX50	Necessary	27.00 FS	*24.30 FS
7	1		*BUMPER FRT BASE SPOI	Not Necessary	233.70 FS	*- FS
8	1		*GRILLE-RADIATOR-Q50	Cracked	979.60 FS	*881.64 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,898.20	905.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER, RADIATOR GRILLE, ETC	New	1,600.00	800.00
2	TO SPRAYPAINT ON FRT BUMPER, ETC	New	1,600.00	800.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	498.00	498.00
Gross Labour Cost (\$)			3,698.00	2,098.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >